



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 8086E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT MUDGUARD	BROKEN	75.00	75.00
1	FRONT WHEEL SHAFT	SCRATCHED	130.00	130.00
1	FRONT WHEEL BEARING	NOT NECESSARY	80.00	-
1	FRONT DISC ROTOR	NOT NECESSARY	200.00	-
2	FRONT FORK ASSY LH & RH @\$240.00	NOT NECESSARY	480.00	-
1	STEM STEERING	NOT NECESSARY	165.00	-
1	HANDLEBAR	NOT NECESSARY	80.00	-
1	CLUTCH LEVER	NOT NECESSARY	40.00	-
1	BRAKE LEVER	SCRATCHED	40.00	40.00
2	BALANCER @\$25.00	SCRATCHED	50.00	50.00
2	SIDE MIRROR @\$30.00	NOT NECESSARY	60.00	-
1	FRONT HEADLAMP COVER	CRACKED	60.00	60.00
2	FRONT SIGNAL LAMP @\$25.00	O/S SCRATCHED	50.00	25.00
1	HEADLIGHT ASSY	NOT NECESSARY	160.00	-
1	FRONT MASK	CRACKED	90.00	90.00
1	FRONT MASK BASE	CRACKED	120.00	120.00
1	PILOT LIGHT	NOT NECESSARY	250.00	-
1	BELLY SHIELD COVERING	SCRATCHED	90.00	90.00
1	FRONT SIDE FAIRING LH	NOT NECESSARY	95.00	-
1	FRONT SIDE FAIRING RH	SCRATCHED	95.00	95.00
1	REAR SIDE FAIRING LH	NOT NECESSARY	95.00	-
1	REAR SIDE FAIRING RH	SCRATCHED	95.00	95.00
1	CENTRE COVERING	SCRATCHED	120.00	120.00
1	FRONT FOOTREST BAR	NOT NECESSARY	75.00	-
2	FRONT FOOTREST RUBBER @\$45.00	NOT NECESSARY	90.00	-
1	GEAR PEDAL	NOT NECESSARY	50.00	-
1	REAR LH FOOT REST	NOT NECESSARY	45.00	-
1	REAR LH FOOT REST BRACKET	NOT NECESSARY	80.00	-
1	EXHAUST PIPE	NOT NECESSARY	400.00	-

Report Ref No. CS/AGI21012632/Rny3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-346.00	-99.00
			3,114.00	891.00
1	FRONT WHEEL (LOCAL REPAIR) (SN)	SCRATCHED	350.00	100.00
	LESS 10% DISCOUNT		-35.00	-
			315.00	100.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT FORK SEAL (SN)	NOT NECESSARY	80.00	-
1	FRONT FORK OIL (SN)	NOT NECESSARY	300.00	-
1	IU UNIT (SN)	SCRATCHED	160.00	140.00
1	NO. PLATE (FRONT) (SN)	NECESSARY	20.00	10.00
1	SET BODY STICKER (SN)	NECESSARY	180.00	100.00
			740.00	250.00
	<b><u>LABOUR</u></b>			
	TOWING.	NOT NECESSARY	100.00	-
	TO REALIGN BODY FRAME.		350.00	250.00
	TO R&R FRONT SUSPENSION, HANDLE BAR, HEADLAMP, SIDE FAIRING, AND ATTACHEMENTS.		400.00	300.00
			850.00	550.00
<b>GRAND TOTAL</b>			<b>5,019.00</b>	<b>1,791.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,400.00</b>

Report Ref No. CS/AGI21012632/Rny3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.