

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21012633/RQF3N2**Date:** 04/05/2022**REFERENCE**

Insured/Claimant: BOK SENG LOGISTIC PRIVATE LIMITED Policy No: D19MFL0000768_02

Date of Loss: 05/12/2021

Nature of Claim: OD

Claim No: MFL2021D0005592

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **XE2706Z**

Make & Model: MAN TGS 18.320, 10.5 D 4X2 BLS (M)

Engine No: 51545361604546

Reg. Date: 10/03/2017 (Man. Year: 2016)

Chassis No: WMA58WZZXHL073344

Colour: Multi-colour

Odometer: 138226 km

Engine Capacity: 12419 cc

Market Value/New Car Price: S\$80,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 385/65 R22.5

Rear Tyre Size: 385/65 R22.5 (D)

Front Left Side: ANNAITE 8 mm

Rear Left Side: ANNAITE 8/8 mm

Front Right Side: ANNAITE 8 mm

Rear Right Side: ANNAITE 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,626.95	3,621.95	5.00	0.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	400.00	650.00	61.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,676.95	4,021.95	655.00	14.00
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
Nett Amount (S\$)	1,676.95	1,021.95	655.00	39.06

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 16/12/2021 Inspected At:

Sin Sheng Auto Workshop Pte Ltd (HQ)

5 TUAS AVE 3

Singapore 639405

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 May 2022)

Parts: N/A MAN TGS 18.320 10.5 D 4X2 BLS (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XE2706Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER TOWING COVERING	Cracked	3,985.50 FL	*3,985.50 FL	
2	1		*FRONT NUMBER PLATE WITH CASING	Bent	40.00 FS	*35.00 FS	
					Sub Total (\$\$)	4,025.50	4,020.50
					- List Item Discount on L Items 10.00/10.00% (\$\$)	398.55	398.55
					Total Parts (\$\$)	3,626.95	3,621.95

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPRAY PAINTING ON AFFECTED AREAS.	New	500.00	200.00
2	TO PANEL BEATING / REPAIR FRONT BODY.TO REMOVE / REPLACE ABOVE MENTIONED PARTS. }	New	550.00	200.00
Gross Labour Cost (\$\$)			1,050.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >