

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012634/KPA3Q2**Date:** 17/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900085534
Claimant Vehicle No :	SKH463A	Insured Vehicle No :	SML277B
Date of Loss:	10/12/2021	Nature of Claim:	TP
		Claim No:	5322660858SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH463A	Engine No:	1AR0457959
Make & Model:	TOYOTA LEXUS, 2.7 RX270 (A)	Chassis No:	JTJZA11A302402243
Reg. Date:	16/02/2011 (Man. Year: 2011)	Odometer:	115287 km
Colour:	Metallic Black		
Engine Capacity:	2672 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Yokohama 3 mm	Rear Left Side:	LAUFENN 8 mm
Front Right Side:	Yokohama 3 mm	Rear Right Side:	LAUFENN 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,461.00	5,952.22	2,508.78	29.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,750.00	1,010.00	36.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,221.00	7,702.22	3,518.78	31.36
Approved Total (Overridden) (S\$)		6,150.00		
(S\$)	11,221.00	6,150.00	5,071.00	45.19
+ GST 7.00/7.00% (S\$)	785.47	430.50	354.97	45.19
Nett Amount (S\$)	12,006.47	6,580.50	5,425.97	45.19
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		7,067.99		

INSPECTION

Date of Assignment:	14/12/2021	
Date Inspected:	14/12/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	1,007.10 FL	*1,007.10 FL
2	1		*FRONT BUMPER SPONGE	Damaged	153.40 FL	*153.40 FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	812.70 FL	*- FL
4	1		*FRONT BUMPER RH FOG LAMP COVER	Serviceable	72.90 FL	*- FL
5	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	138.00 FL	*138.00 FL
6	1		*FRONT BUMPER NUMBER PLATE GARNISH	Cracked	164.80 FL	*164.80 FL
7	6		*FRONT BUMPER CLIPS	Necessary	27.00 FL	*27.00 FL
8	1		*FRONT GRILLE ASSY	Dented	934.90 FL	*934.90 FL
9	1		*FRONT GRILLE INNER TOP GARNISH	Serviceable	367.60 FL	*- FL
10	1		*RH HEADLAMP	Mtg Cracked	2,723.40 FL	*2,723.40 FL
11	1		*REAR BUMPER	Buckled	960.30 FL	*960.30 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	738.10 FL	*738.10 FL
13	1		*REAR BUMPER SPONGE	Cracked	173.10 FL	*173.10 FL
14	1		*REAR BUMPER LH SIDE RETAINER	Distorted	125.40 FL	*125.40 FL
15	1		*REAR BUMPER LH CORNAL RETAINER	Distorted	100.70 FL	*100.70 FL
16	1		*REAR END PANEL	Repair	918.50 FL	*- FL
17	1		*TAILGATE LOGO	Necessary	85.80 FL	*85.80 FL
18	1		*TAILGATE EMBLEM (RX)	Necessary	104.40 FL	*104.40 FL
19	1		*TAILGATE EMBLEM (LEXUS)	Necessary	79.90 FL	*79.90 FL
20	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS
21	1		*UNIT REAR END PANEL SEALANT	Not Necessary	40.00 FS	*- FS
22	1		*SET PARKING SENSORS	Dented / Cracked	1,120.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,883.00	7,831.30
- List Item Discount on L Items 25.00/25.00% (S\$)	2,422.00	1,879.08
Total Parts (S\$)	8,461.00	5,952.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER & ATTACHMENTS ,GRILLE ,HEADLAMP KNOCK & REPAIR FRT PANEL AND REALIGN BONNET THE SAME	New	600.00	300.00
2	PUTTY & RESPRAY FRT BUMPER ,BONNET ,FRT PANEL ,FRT RH FENDER AND ALL AFFECTED AREAS	New	600.00	400.00
3	REMOVE & REFIX REAR BUMPER & ATTACHMENT ,CUT,WELD & RENEW REAR END PANEL KNOCK & REPAIR REAR SPARE TYRE PANEL & REALIGN TAILGATE THE SAME	New	750.00	450.00
4	PUTTY & RESPRAY REAR BUMPER AND PARKING SENSORS ,TAILGATE REAR END PANEL AND ALL AFFECTED AREAS	New	750.00	600.00
5	RUSTPROOFING	New	60.00	0.00
Gross Labour Cost (\$\$)			2,760.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >