

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 9636C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER	CRACKED	653.90	653.90
1	FRT BUMPER RETAINER LH	DISTORTED	34.50	34.50
1	HEADLAMP LH	SERVICEABLE	866.70	-
1	HEADLAMP RETAINER LH	SERVICEABLE	36.50	-
1	FRT FENDER LH	BENT	403.40	403.40
1	LINING ,FRT FENDER LH	DISTORTED	156.00	156.00
1	BONNET	TO REPAIR SEE LABOUR	1,091.70	-
1	FRT DOOR RH	BENT	1,017.00	1,017.00
1	REAR DOOR RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-425.97	-226.48
			3,833.73	2,038.32
	SPECIAL NETT ITEMS			
10	CLIPS ,FRT BUMPER @\$4.00 (SN)	NECESSARY	40.00	40.00
20	CLIPS ,FENDER LINING @\$4.00 (SN)	NECESSARY	80.00	80.00
			120.00	120.00
	<u>LABOUR</u>			
	TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT.STRAIGHTEN CHASSIS MEMBER.REPAIR /RESHAPE DENTED BODY PANEL .REPLACE DAMAGED PART.REFIT INTO POSITION.INCLUSIVE OF THE REPAIR OF BONNET ,REAR DOOR RH,FRT FENDER RH,REAR FENDER RH AND REAR BUMPER .		1,000.00	700.00
	SPRAY PAINTING.		1,800.00	1,200.00

Report Ref No. CC6/TP21012635/Kgs3q2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2	.:2 of 2	No.:2	Page
-----------------	----------	-------	------

4,078.32

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	CHECK WIRING & LIGHT FUNCTION .		50.00	20.00
			2,850.00	1,920.00
	GRAND TOTAL		6,803.73	4,078.32

Report Ref No. CC6/TP21012635/Kgs3q2

KONG SENG CHEONG

Licensed Appraiser