

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21012636/EEA3Q2**Date:** 17/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0004233_01
Claimant Vehicle No : PA9781A **Insured Vehicle No :** XB8546U
 Date of Loss: 13/12/2021 Nature of Claim: TP Claim No: MFL2021D0005611

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PA9781A**
 Make & Model: ISUZU LT134P, 7.8 D (M) Engine No: 6HK1493328
 Reg. Date: 18/11/2010 (Man. Year: 2010) Chassis No: JALLT134PA7000083
 Colour: Multi-colour Odometer: 560638 km
 Engine Capacity: 7790 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R22.5 Rear Tyre Size: 195/80 R22.5
 Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
 Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,075.00	11,686.50	1,388.50	10.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	4,300.00	600.00	12.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,975.00	15,986.50	1,988.50	11.06
Approved Total (Overridden) (S\$)		12,800.00		
(S\$)	17,975.00	12,800.00	5,175.00	28.79
+ GST 7.00/7.00% (S\$)	1,258.25	896.00	362.25	28.79
Nett Amount (S\$)	19,233.25	13,696.00	5,537.25	28.79
+ Loss of Use (12.0 x S\$220.00/day) (S\$)		2,640.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		16,343.45		
Global Sum Settlement (S\$)		16,340.00		

INSPECTION

Date of Assignment: 14/12/2021
 Date Inspected: 15/12/2021 Inspected At: WTS AUTOMOTIVE SERVICES PTE LTD
 8 Gul Circle
 Singapore 629564
 Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 May 2022)	
Parts:	N/A	ISUZU LT134P 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA9781A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	2,060.00 F	*2,060.00 FL
2	1		*REAR BUMPER STRUCTURE FRAME	Dented	1,730.00 F	*1,730.00 FL
3	1		*REAR ENGINE COVER	Dented	1,850.00 F	*1,850.00 FL
4	1		*REAR ENGINE COVER STRUCTURE FRAME	Dented	1,800.00 F	*1,800.00 FL
5	1		*REAR LHS TAIL LAMP	Broken	380.00 F	*380.00 FL
6	1		*REAR LHS CORNER PANEL	Broken	850.00 F	*850.00 FL
7	2		*GAS SPRING	Not Necessary	90.00 F	*- FL
8	1		*60KM/H STICKER	Necessary	5.00 F	*5.00 FL
9	1		*REAR NUMBER PLATE	Broken	30.00 F	*30.00 FL
10	1		*WOODLANDS TRANSPORT STICKER	Necessary	180.00 F	*180.00 FL
11	1		*REAR PANEL (WINDSCREEN LOWER PANEL)	Broken	2,300.00 F	*2,300.00 FL
12	1		*REAR ENGINE COVER INNER METAL STRUCTURE FRAME	Dented	1,800.00 F	*1,800.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	13,075.00	12,985.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,298.50
Total Parts (\$\$)	13,075.00	11,686.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REMOVE ALL NECESSARY ATTACHMENT ITEMS AND DAMAGED ITEMS REPLACE AFFECTED PARTS TO REPAIR AND KNOCK REAR PANEL	New	2,300.00	2,200.00
2	CHECK WIRING SYSTEM AND REMOVE REAR LHS TAIL LAMP AND REPLACE NEW PARTS	New	200.00	100.00
3	SPRAY PAINTING :TO PUTTY AND SPRAY PAINTING REAR BUMPER ,REAR WHOLE ENGINE COVER ,REAR LHS CORNER PANEL AND REAR PANEL TO PATCH REAR WTS STICKER	New	2,400.00	2,000.00
Gross Labour Cost (\$)			4,900.00	4,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >