

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21012638/KQF3E2

Date: 16/02/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001219992
Claimant Vehicle No : GBA1945M Insured Vehicle No : SMD8898Z
Date of Loss: 12/12/2021 Nature of Claim: TP Claim No: 266914

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA1945M**
Make & Model: MERCEDES-BENZ VITO 111, 2.1 D L (M) Engine No: 64698051317929
Reg. Date: 03/04/2007 (Man. Year: 2007) Chassis No: WDF63960323314756
Colour: Metallic Grey Odometer: 524270 km
Engine Capacity: 2148 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 7 mm Rear Left Side: Habilead 8 mm
Front Right Side: Dunlop 7 mm Rear Right Side: Habilead 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,990.30	3,422.30	3,568.00	51.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,645.00	1,570.00	1,075.00	40.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,635.30	4,992.30	4,643.00	48.19
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	9,635.30	3,000.00	6,635.30	68.86

INSPECTION

Date of Assignment: 14/12/2021
Date Inspected: 17/12/2021 Inspected At: Trust Autoworks - Ang Mo Kio (HQ)
Singapore 569538
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Feb 2022)	
Parts:	N/A	MERCEDES-BENZ VITO 111 2.1 D L (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA1945M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S FENDER	Repair	625.00 FL	*- FL
2	1		*FRONT O/S DOOR	Bent	1,850.00 FL	*1,490.00 FL
3	1		*FRONT O/S DOOR RUBBER (50%)	Dented / Cut	165.00 FN	*82.50 F
4	1		*FRONT O/S DOOR PROTECTOR	Bent	185.00 FL	*185.00 FL
5	1		*FRONT O/S DOOR INNER TRIM BOARD	Serviceable	655.00 FL	*- FL
6	1		*FRONT O/S DOOR REGULATOR	Serviceable	325.00 FL	*- FL
7	1		*FRONT O/S DOOR REGULATOR MOTOR	Serviceable	455.00 FL	*- FL
8	1		*FRONT O/S DOOR LOWER HINGE	Bent	145.00 FL	*145.00 FL
9	1		*REAR O/S SLIDING DOOR PROTECTOR	Dented / Cut	205.00 FL	*205.00 FL
10	1		*FRONT O/S SHOCK ABSORBER	Serviceable	405.00 FL	*- FL
11	1		*FRONT O/S LOWER ARM	Serviceable	455.00 FL	*- FL
12	1		*FRONT O/S KNUCKLE ARM	Bent	487.00 FL	*487.00 FL
13	1		*FRONT O/S KNUCKLE ARM BEARING	Necessary	155.00 FL	*155.00 FL
14	1		*FRONT O/S HUB ASSY	Bent	405.00 FL	*405.00 FL
15	1		*FRONT O/S DOOR STICKER	Necessary	25.00 FS	*25.00 FS
16	1		*FRONT & REAR O/S TYRE RIM (2PCS)	Dented(1Pc Only)	1,100.00 FS	*550.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	7,642.00	3,729.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	635.20	307.20
- Nett Item Discount on N Items 10.00/0.00% (\$\$)	16.50	0.00
Total Parts (\$\$)	6,990.30	3,422.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING, WELDING & CUTTING ETC	New	1,000.00	500.00
2	TO PUTTY AND SPRAY PAINT	New	1,000.00	800.00
3	CHECK & RECONNECT WIRING	New	45.00	20.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	120.00	30.00
5	REMOVE / REFIT FRONT O/S DOOR MECHANISM, INNER TRIM, WIPER MOTOR TO NEW DOOR	New	120.00	60.00
6	REMOVE / RENEW FRONT O/S UNDERCARRIAGE	New	280.00	100.00
7	CHECK AND REALIGN WHEEL ALIGNMENT	New	80.00	60.00
			Gross Labour Cost (S\$)	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >