

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012640/UGA3Q2**Date:** 19/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993682
Claimant Vehicle No :	GBK2300P	Insured Vehicle No :	GBK6123H
Date of Loss:	14/12/2021	Nature of Claim:	TP
		Claim No:	5177211757SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK2300P		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KDB017577
Reg. Date:	26/02/2020 (Man. Year: 2019)	Chassis No:	JTFHT02P300249954
Colour:	White	Odometer:	49406 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,116.40	8,263.97	9,852.43	54.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	2,070.00	1,830.00	46.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,016.40	10,333.97	11,682.43	53.06
Approved Total (Overridden) (S\$)		8,200.00		
(S\$)	22,016.40	8,200.00	13,816.40	62.76
+ GST 7.00/7.00% (S\$)	1,541.15	574.00	967.15	62.76
Nett Amount (S\$)	23,557.55	8,774.00	14,783.55	62.76
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,141.45		
Global Sum Settlement (S\$)		9,100.00		

INSPECTION

Date of Assignment:	14/12/2021	
Date Inspected:	14/12/2021	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Shattered	1,499.80 F	*1,399.10 FL
2	1		*REAR WIPER ARM	Not Necessary	245.50 F	*- FL
3	1		*REAR WIPER ARM MOTOR	Not Necessary	655.10 F	*- FL
4	1		*REAR WIPER BLADE	Not Necessary	108.00 F	*- FL
5	1		*TAILGATE	Badly Dented	2,159.10 F	*2,159.10 FL
6	1		*TAILGATE OUTER HANDLE	Cracked	455.80 F	*341.10 FL
7	1		*TAILGATE INNER LOCK	Jammed	425.80 F	*398.50 FL
8	1		*TAILGATE INNER LOCK ACTUATOR	Damaged / Jammed	455.20 F	*366.50 FL
9	1		*TAILGATE LOCK STRIKER	Not Necessary	45.00 F	*- FL
10	1		*TAILGATE WEATHERSTRIP	Twisted	399.80 F	*361.20 FL
11	2		*TAILGATE DAMPERS	Not Necessary	732.20 F	*- FL
12	1		*TAILGATE INNER TRIM BOARD	Deformed / Torn	455.10 F	*421.10 FL
13	1		*TAILGATE REAR LOGO	Necessary	85.00 F	*85.00 FL
14	1		*TAILGATE TOYOTA STICKER	Necessary	60.00 F	*60.00 FL
15	1		*TAILGATE HIACE STICKER	Necessary	62.00 F	*62.00 FL
16	1		*REAR BUMPER	Distorted	681.10 F	*651.20 FL
17	1		*REAR BUMPER STEP BRACKET	Not fitted	166.80 F	*- FL
18	4		*REAR BUMPER LOWER BRACKETS	Bent	140.00 F	*140.00 FL
19	2		*REAR BUMPER SIDE RETAINERS	Cracked	210.00 F	*210.00 FL
20	1		*REAR END PANEL OUTER	Badly Dented	981.10 F	*801.10 FL
21	1		*REAR END PANEL INNER	Badly Dented	988.50 F	*645.20 FL
22	1		*REAR END PANEL TOP STEEL PLATE	Repair	366.80 F	*- FL
23	2		*TAILLAMPS	Cracked	910.20 F	*798.20 FL
24	2		*TAILLAMP LOWER GARNISHS	Deformed / Twisted	330.00 F	*330.00 FL
25	2		*TAILLAMP HOUSING PANELS	Dented / Bent	977.00 F	*816.00 FL
26	1		*REAR SPARE TYRE BRACKET	Repair	455.10 F	*- FL
27	1		*REAR SPARE TYRE BRACKET HOLDER	Not Necessary	165.30 F	*- FL
28	1		*REAR FENDER	Repair	1,971.10 F	*- FL
29	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
30	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
31	1		*REAR LICENCE PLATE	Serviceable	50.00 FS	*- FS
32	1		*SET REAR TAILGATE CORPORATE STICKER	Necessary	500.00 FS	*300.00 FS
33	1		*SET REAR TAILGATE TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
34	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
35	1		*SET REAR BUMPER REVERSE SENSOR	Shorte	280.00 FS	*200.00 FS
36	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
37	1		*REAR WOODEN PLY WOOD	Not Necessary	850.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,116.40	10,775.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,511.33
Total Parts (\$\$)	18,116.40	8,263.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACED REAR WINDSCREEN	New	150.00	100.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO SPRAY RUST PROOFING	New	120.00	80.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	850.00
8	TO PUTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (\$)			3,900.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >