LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/CTI21012644/T1QY3N2

Date:

03/01/2022

REFERENCE

Date of Loss:

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No:

DMHCSNA00006492101

Claimant Vehicle No:

SME4525X 12/12/2021

Insured Vehicle No: Nature of Claim:

ΤP

SLK4366T

Claim No: SNM21D207253/C02/LEWLC

LEB5609337

GB71074390

302964 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME4525X

Make & Model: HONDA FREED HYBRID, 1.5 (A) 28/09/2018 (Man. Year: 2018)

Reg. Date: Colour: Silver

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: No

Engine No:

Chassis No:

Odometer:

CONDITION OF TYRES

Front Left Side:

Front Right Side:

Front Tyre Size:

Rear Tyre Size: 185/60R15 Triangle 6 mm Rear Left Side:

185/60R15 Triangle 6 mm

Triangle 6 mm

Rear Right Side:

Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/12/2021

Trident Auto Service Centre Pte Ltd (HQ) Date Inspected: Inspected At: 8 Kaki bukit Ave 4 #02-44 Premier 20/12/2021

Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
- THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jan 2022)

HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0) Parts: M1-MPV

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SME4525X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >