

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

8 SHENTON WAY #24-01 AXA TOWER Date: 29, SINGAPORE 068811 ATTN: KOH JANICE Code: AS	S/ASM21012647/VAqy3e2 9/03/2022
SINGAPORE 068811 ATTN: KOH JANICE Code: AS	9/03/2022
	SM
1. Policy Particulars :- THIRD PARTY CLAIM	
Insured Veh. EP 6688H Veh. Inspected SL	LE 435K
Policy No. GA294729/1 Coverage (\$) 0.0	00
Claim No. S1M03O1E Excess (\$) 0.0	00
Assign From KOH JANICE Assign Date 14/	1/12/2021
2. Vehicle Particulars & Condition	
Make & Model B.M.W. 218I COUPE c.c 148	199
Engine No. HIDDEN Year of Reg. 20	016
Chassis No. WBA2F12040V758238 Colour WH	HITE
Odometer 117329 KM Steering IN	ORDER
Brakes IN ORDER Modification SP	PORTS RIM
General GOOD	
3. Conditions of Tyres	
Size Make Ba	alance
R/H Front Tyre 225/40 R18 CONTINENTAL 6 n	mm
L/H Front Tyre 225/40 R18 CONTINENTAL 6 n	mm
R/H Rear Tyre 225/40 R18 CONTINENTAL 6 n	mm
L/H Rear Tyre 225/40 R18 CONTINENTAL 6 n	mm
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.	
DAMAGES SEE DETAILS.	
5. General Information	
Accident Date 11/12/2021 Inspection Date 14/	1/12/2021
Survey held at YSK AUTO WORKSHOP	
1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883	
5a. Remarks	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working	Days