

SHE435K 2016 June.

TPAXA.

BMW 218i Coupe 1499cc

Xiao Chan.

WBA2F12040V758238

Rear Bumper	Distorted	1285	✓
Rear Bumper Clips.	m	50(SN)	✓
Rear Bumper Side Holder x 02	RH mtd	68 x 2 = 136	68
Rear Bumper Tow Cover	Weld	38	✓
Rear Bumper Reflector RH	Weld	85	✓
Rear Bumper Centre Guide	Weld	192	✓
Rear Bumper Reinforcement	Dented	548.	✓
Rear Bumper Lower Spoiler	Dented	1200(SN)	1000(SN)
Rear Bumper Undercover RH	m	95	x
Reverse Sensor x 02	10124 L	260 x 2 = 520	✓
Reverse Sensor Holder x 04	m	20 x 4 = 80	✓
Rear End Panel	Ryis	1018	x
Rear End Panel Top Garnish	xp	322	x
Rear End Panel Sealant	m	60(SN)	x

SLE4351C.

Tail lamp RH. ^{lit} 695 /
 Rear Exhaust Chrome Pipe RH. ^{Best} ~~320 (SN)~~ 200 (SN)
 Bootlid Lock } 345 +
 Bootlid Weatherstripe. } ^{lit m} 313. +
 BMW Logo. 85 +.

3511 S.N. 1250
 3759.90

Panel Beauty ~~800~~ 400
 Spray Painting ~~600~~ 500
 Wiring ~~50~~ 30
 To remove reuse sensor ~~100~~ 60
 To remove upholstery. ~~150~~ 40
 To spray full coat 100 50
 To perform diagnostic test. 200. x.

total: 5489.90

4/8: A.A.K.

04 Days

(A.A.K)

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: