

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21012649/UVY3E2

Date: 30/12/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00098742100

**Claimant Vehicle
No :** SKW8279J

**Insured
Vehicle No :** GBL4905B

Date of Loss: 11/12/2021

Nature of Claim: TP

Claim
No: SNM21D207258/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW8279J**

Make & Model: MAZDA 3, 1.5 (A)

Engine No: P520330003

Reg. Date: 18/11/2015 (Man. Year: 2015)

Chassis No: JM6BM42A8G0324327

Colour: Silver

Odometer: 193817 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,647.44	5,311.20	1,336.24	20.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,450.00	1,330.00	47.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,427.44	6,761.20	2,666.24	28.28
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	9,427.44	5,400.00	4,027.44	42.72

INSPECTION

Date of Assignment: 17/12/2021

Date Inspected: 15/12/2021 Inspected At:

Eunos Motor Service (HQ)
1 Kaki Bukit Ave 6, #01-64 AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2021)
Parts: 144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKW8279J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BOOTLID	Dented	1,004.00 FL	*1,004.00 FL	
2	2		*REAR BOOTLID HINGE	Serviceable	306.00 FL	*- FL	
3	1		*REAR BOOTLID LOCK	Bent	186.00 FL	*164.60 FL	
4	1		*REAR BOOTLID WEATHERSTRIP	Twisted	136.00 FL	*136.00 FL	
5	1		*REAR BOOTLID EMBLEM MAZDA 3	Necessary	55.80 FL	*55.80 FL	
6	1		*REAR BOOTLID EMBLEM LOGO	Necessary	77.00 FL	*65.80 FL	
7	1		*REAR BOOTLID EMBLEM SKYACTIV TECHNOLOGY EMBLEM	Necessary	66.80 FL	*66.80 FL	
8	2		*REAR BOOTLID LAMP LH / RH	Cracked	932.00 FL	*825.00 FL	
9	1		*REAR BOOTLID INNER CUSHION COVER	Not Necessary	126.00 FL	*- FL	
10	2		*REAR TAIL LAMP LH / RH	Cracked	1,920.00 FL	*1,830.00 FL	
11	2		*REAR BUMPER SIDE RETAINER	Not Necessary	76.00 FL	*- FL	
12	1		*REAR BUMPER CENTRE RETAINER	Cracked	145.00 FL	*145.00 FL	
13	2		*REAR BUMPER REFLECTOR	Not Necessary	106.00 FL	*- FL	
14	1		*REAR BUMPER REINFORCEMENT	Dented	563.00 FL	*563.00 FL	
15	1		*REAR END PANEL	Dented / Bent	530.00 FL	*435.70 FL	
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	99.70 FL	*- FL	
17	1		*SET REAR BUMPER CLIPS	Necessary	96.00 FL	*50.00 FL	
18	1		*SET REAR BUMPER SENSOR	Shorted	463.20 FS	*200.00 FS	
19	2		*REAR NUMBER PLATE LAMP	Not Necessary	90.00 FL	*- FL	
20	1		*REAR NUMBER PLATE LAMP GARNISH	Not Necessary	88.00 FL	*- FL	
21	1		*REAR BUMPER	Dented	1,127.00 FL	*1,047.30 FL	
					Sub Total (S\$)	8,193.50	6,589.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,546.06	1,277.80
					Total Parts (S\$)	6,647.44	5,311.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
2	PANEL BEATING, TO RENEW & REPLACE PARTS	New	1,500.00	600.00
3	SPRAY PAINTING AFFECTED AREAS	New	1,200.00	800.00
			Gross Labour Cost (\$)	2,780.00
				1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >