

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21012650/GQF3E2

Date: 28/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLZ4876J

Insured Vehicle No : SMH4619T

Date of Loss: 12/12/2021

Nature of Claim: TP

Claim No: 8338451140SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ4876J**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB6549184

Reg. Date: 04/05/2018 (Man. Year: 2018)

Chassis No: GP71207461

Colour: Blue

Odometer: 64301 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 16/12/2021 Inspected At:

Auto Dynamac Service Trading (HQ)

BLK 3019A UBI ROAD 1, #01-28

Singapore 408713

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$68,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Cut	0.00 F	*- F
3	1		*REAR BUMPER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
6	1		*REAR END PANEL	Buckled	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Cut	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Cut	0.00 F	*- F
10	1		*TAILGATE	Buckled	0.00 F	*- F
11	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
12	1		*TAILGATE OUTER HANDLE	Deformed	0.00 F	*- F
13	2		*TAILGATE LAMP	Cut	0.00 F	*- F
14	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
15	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
16	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
17	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F
18	1		*SPARE TYRE PANEL	Buckled	0.00 F	*- F
19	1		*REAR LH FENDER INNER TRIM	Cracked	0.00 F	*- F
20	1		*REAR RH FENDER INNER TRIM	Cracked	0.00 F	*- F
21	1		*SPARE TYRE TOOL BOX	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >