

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012651/EQY3N2**Date:** 06/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00075892100

Claimant Vehicle No : SLC105Z **Insured Vehicle No :** SJK2614P

Date of Loss: 10/12/2021 Nature of Claim: TP Claim No: SNM21D207239/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC105Z**

Make & Model: VOLKSWAGEN JETTA, 1.4 (A) Engine No: CAXF83808

Reg. Date: 28/04/2016 (Man. Year: 2015) Chassis No: WVVZZZ16ZGM018992

Colour: Red Odometer: 75378 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,302.13	11,382.33	5,919.80	34.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,455.00	10,015.00	7,440.00	42.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,757.13	21,397.33	13,359.80	38.44
+ GST 7.00/7.00% (S\$)	2,433.00	1,497.81	935.19	38.44
Nett Amount (S\$)	37,190.13	22,895.14	14,294.99	38.44

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 15/12/2021 Inspected At: Volkswagen Centre Singapore (Tuas)
17 TUAS AVENUE
Singapore 639176

Estimated Period of Repair: 11.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$3,153.73 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2022)
Parts:	143	VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC105Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD FRT BONNET	Repair	1,217.06 FS	*- FS
2	1		*COVER FOR BUMPER PRIMED FRT BUMPER	Repair	1,363.08 FS	*- FS
3	1		*GUIDE PIECE FRT BUMPER SIDE BRACKET LH	Broken	37.17 FS	*37.17 FS
4	1		*GUIDE PIECE FRT BUMPER SIDE BRACKET RH	Broken	37.17 FS	*37.17 FS
5	1		*GAS DISCHARGE HEADLIGHT W LHS H/LAMP	Broken	3,681.62 FS	*3,681.62 FS
6	1		*GAS DISCHARGE HEADLIGHT W RHS H/LAMP	Cut	3,681.62 FS	*3,681.62 FS
7	2		*FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING	*Check	43.30 FS	*- FS
8	1		*FENDER LH	Dented	631.36 FS	*631.36 FS
9	1		*CROSS SUPPORT LHS FENDER BRACKET	Necessary	51.67 FS	*51.67 FS
10	1		*WHEELHOUSE LINER LHS FENDER LINER	Not Necessary	185.93 FS	*- FS
11	1		*FENDER RH	Dented	631.36 FS	*631.36 FS
12	1		*WHEELHOUSE LINER RHS FENDER LINER	Necessary	51.67 FS	*51.67 FS
13	1		*WHEELHOUSE LINER RHS FENDER LINER	Crushed	185.93 FS	*185.93 FS
14	6		*EXPANDING NUT	Necessary	11.04 FS	*11.04 FS
15	1		*VW SIGN CHROME COLORED/BIREAR BOOT LID NAME PLATE VW	Necessary	99.29 FS	*99.29 FS
16	1		*INSCRIPTION BRILLIANT CHR NAME PLATE-JETTA	Necessary	70.95 FS	*70.95 FS
17	1		*INSCRIPTION CHROME/RED NAME PLATE-TSI	Necessary	65.63 FS	*65.63 FS
18	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Dented	1,359.58 FS	*1,359.58 FS
19	1		*SENSOR BRACKET	Necessary	17.03 FS	*17.03 FS
20	2		*SENSOR BRACKET	Necessary	34.06 FS	*34.06 FS
21	1		*SENSOR BRACKET	Necessary	17.03 FS	*17.03 FS
22	1		*2-PACK POLYURETHANE ADHES	Necessary	73.08 FS	*73.08 FS
23	1		*BONDING AGENT FOR PLASTIC	Necessary	65.42 FS	*65.42 FS
24	1		*SPOILER	Broken	504.36 FS	*504.36 FS
25	1		*BUMPER REINFORCEMENT	*Check	652.80 FS	*- FS
26	1		*ATTACHMENT STRIP RR BUMPER CTR BRACKET	*Check	85.30 FS	*- FS
27	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	*Check	91.69 FS	*- FS
28	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	*Check	91.69 FS	*- FS
29	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	*Check	91.69 FS	*- FS
30	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	*Check	91.69 FS	*- FS
31	1		*TAILLIGHT LHS TAILLIGHT OUTER	*Check	442.71 FS	*- FS
32	1		*REFLECTOR LHS REFLECTOR	Broken	75.29 FS	*75.29 FS
33	1		*EXHAUST SILENCER REAR	*Check	1,500.51 FS	*- FS
34	1		*DUAL CLAMP	*Check	62.35 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 17,302.13 11,382.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING ASSISTANCE-AWP	New	195.00	195.00
2	LABOUR FRT	New	4,200.00	2,520.00
3	SPRAY PAINT FRT	New	4,000.00	3,200.00
4	LABOUR REAR	New	4,200.00	840.00
5	SPRAY PAINT REAR	New	4,000.00	2,400.00
6	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
7	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
8	TO ALIGN LED HEADLIGHT	New	100.00	100.00
Gross Labour Cost (\$)			17,455.00	10,015.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >