

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CS/AIG21012654/KQF3N2

Date:

03/01/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

7210105665

Claimant Vehicle No : SJN6205U**Insured Vehicle No :**

SJP9198B

Date of Loss: 11/12/2021

Nature of Claim:

TP

Claim No:

3538101436SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJN6205U**

Make & Model: TOYOTA ALLION, 1.5 (A)

Reg. Date: 23/02/2009 (Man. Year: 2008)

Colour: Metallic Silver

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No:

1NZD224627

Chassis No:

NZT2603034139

Odometer:

317879 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70R14

Rear Tyre Size:

185/70R14

Front Left Side: Falken 9 mm

Rear Left Side:

Falken 7 mm

Front Right Side: Falken 9 mm

Rear Right Side:

Falken 7 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,594.02	2,145.75	448.27	17.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,795.00	850.00	945.00	52.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,389.02	2,995.75	1,393.27	31.74
Approved Total (Overridden) (S\$)		2,400.00		

Nett Amount (S\$)**4,389.02****2,400.00****1,989.02****45.32**INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 15/12/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Massive Trading & Auto
Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2
Singapore 569541**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S HEADLAMP ASSY	Cracked	1,055.60 FL	*1,050.10 FL
2	1		*FRONT RADIATOR GRILLE	Serviceable	235.60 FL	*- FL
3	1		*FRONT BUMPER-COLOUR CODE	Buckled	1,050.80 FL	*1,020.10 FL
4	1		*FRONT N/S BUMPER SIDE RETAINER	Distorted	65.70 FL	*65.70 FL
5	1		*FRONT N/S FOG LAMP GARNISH	Serviceable	75.10 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE	Serviceable	145.60 FL	*- FL
7	1		*FRONT N/S FENDER	Bent	685.10 FL	*685.10 FL
8	1		*FRONT N/S FENDER INNERSHIELD	Serviceable	105.20 FL	*- FL
9	15		*FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	3,448.70
					- List Item Discount on L Items 25.00/25.00% (\$)	854.68
					Total Parts (\$)	2,594.02
						2,145.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING ETC	New	800.00	400.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	800.00	400.00
3	CHECK/RECONNECT WIRING	New	45.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	150.00	30.00
Gross Labour Cost (\$\$)			1,795.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >