

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012658/EVF3N2**Date:** 04/01/2022**REFERENCE**

Insured/Claimant: LIU JUNLIN CHRIS Policy No: 1900018087
Date of Loss: 13/12/2021 Nature of Claim: OD Claim No: 8285969495SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG8808T**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGJH720904
Reg. Date: 20/02/2019 (Man. Year: 2018) Chassis No: KNAF3416MK5030888
Colour: Red Odometer: 38124 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$69,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Kumho 5 mm Rear Left Side: Kumho 5 mm
Front Right Side: Kumho 5 mm Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,046.00	2,766.00	5,280.00	65.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	2,750.00	1,580.00	36.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,376.00	5,516.00	6,860.00	55.43
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	12,076.00	5,216.00	6,860.00	56.81
+ GST 7.00/7.00% (S\$)	845.32	365.12	480.20	56.81
Nett Amount (S\$)	12,921.32	5,581.12	7,340.20	56.81

INSPECTION

Date of Assignment: 14/12/2021
Date Inspected: 15/12/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
2	1		*HINGE ASSY-HOOD,LH	Bent	43.00 FL	*43.00 FL
3	1		*HINGE ASSY-HOOD,RH	Bent	43.00 FL	*43.00 FL
4	1		*LATCH ASSY-HOOD	Not Necessary	103.00 FL	*- FL
5	13		*CLIP-HOOD INSULATING PAD MTG	Not Necessary	13.00 FL	*- FL
6	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 FL	*- FL
7	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
8	1		*GARNISH-RADIATOR GRILLE	Broken	38.00 FL	*38.00 FL
9	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FL	*328.00 FL
10	1		*COVER-FR BUMPER	Crushed	633.00 FL	*633.00 FL
11	1		*GRILLE-FRONT BUMPER	Cut	485.00 FL	*485.00 FL
12	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
13	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
14	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
15	1		*WIRING ASSY-BUMPER EXTENSION	Not Necessary	207.00 FL	*- FL
16	1		*MOULDING-FRONT BUMPER,LH	Cut	216.00 FL	*216.00 FL
17	1		*MOULDING-FRONT BUMPER,RH	Not Necessary	216.00 FL	*- FL
18	1		*LAMP ASSY-SIDE REPEATER,LH	Not Necessary	143.00 FL	*- FL
19	1		*LAMP ASSY-SIDE REPEATER,RH	Not Necessary	143.00 FL	*- FL
20	1		*LAMP ASSY-HEAD,LH	Not Necessary	2,210.00 FL	*- FL
21	1		*LAMP ASSY-HEAD,RH	Not Necessary	2,210.00 FL	*- FL
22	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
23	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
24	1		*BODY PNL SEALANT	Necessary	60.00 FS	*40.00 FS
25	1		*FR NUMBER PLATE WITH CASING	Cut	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,025.00	3,430.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,979.00	664.00
Total Parts (\$\$)	8,046.00	2,766.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER,BONNET & FR SUPPORT REPAIR LHF FENDER & RHF FENDER	New	2,000.00	600.00
2	RESPRAY FR BUMPER,BONNET,LHF FENDER & RHF FENDER	New	1,920.00	1,920.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	0.00
4	TOP UP AC GAS	New	80.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	REMOVE & REFIT FR PARKING ASSIST SENSOR	New	80.00	80.00
Gross Labour Cost (\$\$)			4,330.00	2,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >