



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 1337E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	TORN	1,580.00	1,580.00
1	FRONT BUMPER SIDE HOLDER LH	NOT NECESSARY	85.00	-
1	FRONT BUMPER SENSOR	NOT NECESSARY	265.00	-
1	FRONT BUMPER NOZZLE PUMP	NOT NECESSARY	219.00	-
1	HEADLAMP LH	CUT	2,650.00	2,650.00
	LESS 10% DISCOUNT		-	-423.00
			4,799.00	3,807.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		400.00	250.00
	SPRAY PAINTING.		400.00	250.00
	WIRING.		50.00	30.00
			850.00	530.00
	<b>GRAND TOTAL</b>		<b>5,699.00</b>	<b>4,387.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,500.00</b>

Report Ref No. CS/SMO21012660/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.