

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012662/KTY3N2**Date:** 13/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW0009482102

Claimant Vehicle No : GBF4322P **Insured Vehicle No :** GBH7083Z

Date of Loss: 10/12/2021 Nature of Claim: TP Claim No: SNM21D207195/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF4322P**

Make & Model: NISSAN CABSTAR, 3.0 (M) Engine No: ZD30014022N

Reg. Date: 21/10/2016 (Man. Year: 2016) Chassis No: JN1SC2F24Z0859013

Colour: Silver Odometer: 153715 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195R15X8 Rear Tyre Size: 155R12X8(D)

Front Left Side: KAPSEN 5 mm Rear Left Side: Arivo 3/3 mm

Front Right Side: KAPSEN 5 mm Rear Right Side: Arivo 3/3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,513.81	2,589.91	923.90	26.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	1,310.00	510.00	28.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,333.81	3,899.91	1,433.90	26.88
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	5,333.81	3,050.00	2,283.81	42.82
+ GST 7.00/7.00% (S\$)	373.37	213.50	159.87	42.82
Nett Amount (S\$)	5,707.18	3,263.50	2,443.68	42.82

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 27/12/2021 Inspected At: Falcon Air Auto Services Pte Ltd (HQ)
176 Sin Ming Drive #01-06, Sin Ming Autocare
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 13 Jan 2022)	
Parts:	N/A	NISSAN CABSTAR 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF4322P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,459.60 FN	*1,395.70 FN
2	1		*TAILGATE STICKER (NISSAN)	Necessary	169.00 FN	*169.00 FN
3	1		*REAR END PANEL	Bent	846.80 FN	*458.00 FN
4	1		*LH TAILGATE LOCK	Distorted	56.00 FN	*56.00 FN
5	1		*LH CORNER PANEL	Bent	182.90 FN	*182.90 FN
6	1		*LH CORNER PANEL RUBBER (2 Pcs)	Cut (1 Pc only)	24.00 FN	*12.00 FN
7	1		*LH TAILLAMP (2 Pcs)	Cracked (1 Pc only)	532.60 FN	*266.30 FN
8	1		*70KM/H STICKER	Necessary	25.00 FS	*12.00 FS
9	1		*STICKER-13 PAX	Necessary	25.00 FS	*12.00 FS
10	1		*REAR STEP PANEL	Bent	200.00 FS	*80.00 FS
11	1		*SET REVERSE SENSOR	Cracked	280.00 FS	*200.00 FS
12	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	3,840.90	2,843.90
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	327.09	253.99
Total Parts (\$\$)	3,513.81	2,589.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUSTPROOF ACCIDENT DAMAGE AREA	New	150.00	60.00
2	TO REMOVE/REFIT REVERSE SENSOR INTO NEW BUMPER	New	50.00	50.00
3	TO TRANSFER SLIDING DOOR MECHANISM	New	120.00	0.00
4	TO CUT OUT/REWELD REAR END PANEL,REPAIR REAR FLOOR BOARD,REAR CHASSIS INCLUDING REPLACEMENT OF PARTS	New	700.00	600.00
5	TO SPRAY PAINT ON TAILGATE,REAR END PANEL,REAR FLOOR BOARD	New	800.00	600.00
			Gross Labour Cost (\$)	1,820.00
				1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >