

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012664/VPSAQ2**Date:** 13/04/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SHA9807E **Insured Vehicle No :** SJU1898R
 Date of Loss: 11/12/2021 Nature of Claim: TP Claim No: 1048978084SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA9807E**
 Make & Model: HYUNDAI AE IONIQ, 1.6 (A) Engine No: G4LEKU389512
 Reg. Date: 27/08/2020 (Man. Year: 2019) Chassis No: KMHC851CVLU184468
 Colour: Yellow Odometer: 216085 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,113.36	0.00	1,113.36	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	220.00	160.00	60.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,333.36	160.00	1,173.36	88.00
+ GST 7.00/7.00% (S\$)	93.34	11.20	82.14	88.00
Nett Amount (S\$)	1,426.70	171.20	1,255.50	88.00
+ Loss of Use (1.0 x S\$50.00/day) (S\$)		50.00		
+ Car Rental (1.0 x S\$125.19/day) (S\$)		125.19		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		348.39		
Global Sum Settlement (S\$)		340.00		

INSPECTION

Date of Assignment: 14/12/2021
 Date Inspected: 14/12/2021 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 1.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT RH WING MIRROR	Repair	1,391.70 FL	*- FL	
F=Franchise part. L=ListItemDisc.							
					Sub Total (S\$)	1,391.70	0.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	278.34	0.00
					Total Parts (S\$)	1,113.36	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	120.00	80.00
2	SPRAY PAINTING CHARGE	New	100.00	80.00
			Gross Labour Cost (S\$)	160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >