

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21012671/KPA3Q2**Date:** 17/02/2023REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SLP5793K**Insured Vehicle No :** GBE3931T

Date of Loss: 09/12/2021

Nature of Claim: TP

Claim No: 8770309580SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLP5793K**

Make &amp; Model: MINI COOPER, 1.5 (A)

Engine No: 31799932B38A15A

Reg. Date: 09/06/2017 (Man. Year: 2017)

Chassis No: WMWXS520102F22501

Colour: Metallic White/Red

Odometer: 65272 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17

Rear Tyre Size: 205/45 R17

Front Left Side: Pirelli 7 mm

Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 7 mm

Rear Right Side: Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,089.60	1,333.20	756.40	36.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	670.00	2,480.00	78.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,239.60</b>	<b>2,003.20</b>	<b>3,236.40</b>	<b>61.77</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>366.77</b>	<b>140.22</b>	<b>226.55</b>	<b>61.77</b>
<b>Nett Amount (S\$)</b>	<b>5,606.37</b>	<b>2,143.42</b>	<b>3,462.95</b>	<b>61.77</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		180.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,325.42</b>		

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 15/12/2021 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)  
Blk 1 Sin Ming Industrial Estate Sector C,  
#01/111/113/115/117  
Singapore 575636

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,116.00 FL	*1,116.00 FL
2	1		*FRONT GRILLE	Dented	231.00 FL	*231.00 FL
3	1		*FRONT GRILLE TRIM	Serviceable	125.00 FL	*- FL
4	1		*MINI FRONT HOOD RH	Repair	70.00 FL	*- FL
5	1		*MINI FRONT HOOD LH	Repair	70.00 FL	*- FL
6	1		*MINI LOGO EMBLEM	Dented	66.00 FL	*66.00 FL
7	1		*FRONT BUMPER REINFORCEMENT BAR	Repair	378.00 FL	*- FL
8	1		*IMPACT ABSORBER SPONGE	Serviceable	53.00 FL	*- FL
9	1		*ENGINE BONNET SEAL	Dented / Cut	35.00 FL	*35.00 FL
10	2		*ANTI-RUST COATING	Necessary	160.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,304.00	1,478.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	214.40	144.80
Total Parts (\$\$)	2,089.60	1,333.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	1,500.00	400.00
2	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	1,500.00	250.00
3	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	150.00	20.00
<b>Gross Labour Cost (\$)</b>			<b>3,150.00</b>	<b>670.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >