

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012672/VPA3Q2**Date:** 15/08/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHC3496Y**Insured Vehicle No :** GBC3686L

Date of Loss: 11/12/2021

Nature of Claim:

TP

Claim No: 6237312569SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC3496Y**

Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A)

Engine No: G4LEKU298672

Reg. Date: 24/07/2019 (Man. Year: 2019)

Chassis No: KMHC851CVKU164831

Colour: Blue

Odometer: 342150 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,479.56	846.12	633.44	42.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	820.00	130.00	13.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,429.56	1,666.12	763.44	31.42
+ GST 7.00/7.00% (S\$)	170.07	116.63	53.44	31.42
Nett Amount (S\$)	2,599.63	1,782.75	816.88	31.42
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$128.40/day) (S\$)		385.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,319.95		
Global Sum Settlement (S\$)		2,300.00		

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 14/12/2021 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MOULDING -REAR BUMPER LWR	Serviceable	155.00 FL	*- FL
2	1		*PROTECTOR MAT	Necessary	50.00 FS	*50.00 FS
3	1		*MOULDING ASSY -RR BUMPER C	Distorted / Shorted	451.25 FL	*451.25 FL
4	1		*BEAM -RR BUMPER	Serviceable	394.80 FL	*- FL
5	10		*BUMPER COVER CLIP REAR	Necessary	22.00 FL	*22.00 FL
6	1		*LAMP ASSY -REAR FOG	Serviceable	201.50 FL	*- FL
7	1		*ANTENNA ASSY -SMARTKEY	Serviceable	40.50 FL	*- FL
8	1		*VEHICLE NUMBER PLATE REAR	Cracked	50.00 FS	*50.00 FS
9	1		*COVER -RR BUMPER	Dented	459.40 FL	*459.40 FL
					Sub Total (\$\$)	1,824.451,032.65
					- List Item Discount on L Items 20.00/20.00% (\$\$)	344.89186.53
					Total Parts (\$\$)	1,479.56846.12

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	20.00
4	RENEW ADVERTISEMENT STICKER	New	200.00	200.00
Gross Labour Cost (\$\$)			950.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >