

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21012673/REA3Q2**Date:** 20/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210006861
Claimant Vehicle No :	SHB5064C	Insured Vehicle No :	SDP9788U
Date of Loss:	10/12/2021	Nature of Claim:	TP
		Claim No:	1133711308SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5064C		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR8275621
Reg. Date:	19/12/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU303578381
Colour:	Maroon	Odometer:	239785 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,333.94	2,311.44	20,022.50	89.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,230.00	1,920.00	4,310.00	69.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,563.94	4,231.44	24,332.50	85.19
Approved Total (Overridden) (S\$)		3,750.00		
Nett Amount (S\$)	28,563.94	3,750.00	24,813.94	86.87
+ Loss of Use (8.0 x S\$50.00/day) (S\$)		400.00		
+ Car Rental (8.0 x S\$85.00/day) (S\$)		680.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		4,837.00		

INSPECTION

Date of Assignment:	13/12/2021	
Date Inspected:	13/12/2021	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FR BUMPER (DISC 25%)	Scratched	495.50 F	*371.63 F
2	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	15.00 F	*11.25 F
3	1		*FENDER SUB-ASSY ,FR RH (DISC 25%)	Bent	933.10 F	*699.83 F
4	1		*EMBLEM SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
5	1		*CAP SUB-ASSY ,WHEEL (DISC 25%)	Missing	175.80 F	*131.85 F
6	1		*PANEL SUB-ASSY ,FRONT DOOR RH (DISC 25%)	Bent	1,249.60 F	*937.20 F
7	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
8	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
9	1		*LAMP ASSY ,FOG ,RH	Not Necessary	910.20 F	*- F
10	1		*SUPPORT FR BUMPER RH	Not Necessary	76.90 F	*- F
11	1		*COVER ASSY ,ENGIEN	Not Necessary	180.10 F	*- F
12	1		*UNIT HEADLAMP ,RH	Not Necessary	2,558.90 F	*- F
13	1		*COMPUTER SUB- ASSY HEADLAMP RH NO.1	Not Necessary	486.40 F	*- F
14	1		*LINER ,FR FENDER RH	Not Necessary	198.40 F	*- F
15	1		*PAD FR WHEEL RH	Not Necessary	57.70 F	*- F
16	1		*SEAL SUB-ASSY RH	Not Necessary	50.20 F	*- F
17	1		*PROTECTOR ,FR FENDER RH	Not Necessary	90.40 F	*- F
18	1		*APRON SUB-ASSY ,FRONT FENDER RH	Not Necessary	944.20 F	*- F
19	2		*HUB & BEARING ASSY RH & LH	Not Necessary	554.20 F	*- F
20	1		*TYRE	Not Necessary	126.74 F	*- F
21	1		*MIRROR ASSY ,OUTER REAR VIEW RH	Not Necessary	1,373.50 F	*- F
22	1		*COVER OUTER MIRROR RH	Not Necessary	89.50 F	*- F
23	1		*CHECK ASSY ,FRONT DOOR	Not Necessary	153.50 F	*- F
24	1		*HINGE ASSY ,FRONT DOOR UPPER RH	Not Necessary	82.10 F	*- F
25	1		*HINGE ASSY ,FRONT DOOR LOWER RH	Not Necessary	92.10 F	*- F
26	1		*DOOR FRONT WINDOW REGULATOR SUB-ASSY ,RH	Not Necessary	230.80 F	*- F
27	1		*DOOR FRONT MOTOR ASSY ,POWER WINDOW	Not Necessary	768.60 F	*- F
28	1		*DOOR OUTER HANDLE FRONT RH	Not Necessary	378.90 F	*- F
29	1		*PILLAR CENTER BODY ,OUTER RH	Not Necessary	313.40 F	*- F
30	1		*WIRE FRONT DOOR RH	Not Necessary	445.70 F	*- F
31	1		*HINGE ASSY ,REAR DOOR UPPER RH	Not Necessary	83.30 F	*- F
32	1		*HINGE ASSY ,REAR DOOR LOWER RH	Not Necessary	73.30 F	*- F
33	1		*DOOR REAR MOTOR ASSY POWER WINDOW	Not Necessary	768.60 F	*- F
34	1		*DOOR REAR WINDOW REGULATOR SUB-ASSY ,RH	Not Necessary	200.70 F	*- F
35	1		*CHECK ASSY ,REAR DOOR	Not Necessary	153.50 F	*- F
36	1		*PANEL SUB-ASSY ,FENDER REAR RH	Not Necessary	824.80 F	*- F
37	2		*PATCH SIDE PANEL ,REAR END RH & LH	Not Necessary	33.70 F	*- F
38	1		*LINER ,REAR FENDER RH	Not Necessary	135.80 F	*- F
39	1		*WHEEL DISC	Not Necessary	1,555.10 F	*- F
40	1		*CAP SUB -ASSY WHEEL	Not Necessary	175.80 F	*- F
41	2		*HUB & BEARING ASSY RH & LH	Not Necessary	554.20 F	*- F
42	1		*COVER ,RR BUMPER ASSY	Not Necessary	423.90 F	*- F
43	2		*PAD ,RR BUMPER RH & LH 1	Not Necessary	3.80 F	*- F
44	2		*PAD ,RR BUMPER RH & LH 2	Not Necessary	3.80 F	*- F
45	2		*PAD ,RR BUMPER RH & LH 3	Not Necessary	3.80 F	*- F
46	1		*PAD ,RR BUMPER CTR	Not Necessary	2.20 F	*- F
47	2		*SEAL ,RR BUMPER ARM ,RH & LH	Not Necessary	11.00 F	*- F
48	1		*RETAINER ,RR BUMPER ,RH	Not Necessary	112.70 F	*- F
49	1		*CLIPS PIECE ,FRT & RR BUMPER	Not Necessary	1.50 F	*- F
50	1		*GUARD ,RR BUMPER LOWER	Not Necessary	558.30 F	*- F
51	1		*COVER ,GUARD ,RR BUMPER LOWER	Not Necessary	14.80 F	*- F
52	1		*PIXEL STICKER	Not Necessary	60.00 F	*- F
53	1		*WHEEL DISC FRONT	Repair	1,555.10 F	*- F
54	1		*MOULDING ASSY ,BODY ROCKER PANEL ,RH	Repair	576.00 F	*- F
55	1		*PANEL SUB-ASSY ,REAR DOOR RH	Repair	1,243.90 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part.						
Total Parts (S\$)					22,333.94	2,311.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,264.00	600.00
2	SPRAY PAINT	New	3,906.00	1,130.00
3	TO DOR WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	40.00
4	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
5	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	240.00	30.00
6	TO TRANSFER DOOR MECHANISM	New	240.00	60.00
7	TO APPLY RUST PROOFING ON AFFECTED AREA	New	100.00	60.00
8	TO REPLACE SUNDRY PARTS	New	100.00	0.00
9	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
10	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			6,230.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >