

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012674/AGA3Q2
Date: 18/04/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100475245
Claimant Vehicle No :	YN278X	Insured Vehicle No :	GY273P
Date of Loss:	11/12/2021	Nature of Claim:	TP
		Claim No:	7443855200SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN278X	Engine No:	4M42A73381
Make & Model:	MITSUBISHI FE83BEOSRDEA, 3.0 D B31 (A)	Chassis No:	FE83BEA20044
Reg. Date:	15/06/2009 (Man. Year: 2009)	Odometer:	300653 km
Colour:	Green		
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	7.00 R16	Rear Tyre Size:	185 R14C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,596.03	2,525.01	14,071.02	84.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,440.00	1,230.00	4,210.00	77.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,036.03	3,755.01	18,281.02	82.96
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	22,036.03	3,000.00	19,036.03	86.39
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,436.45		
Global Sum Settlement (S\$)		3,400.00		

INSPECTION

Date of Assignment:	14/12/2021	
Date Inspected:	20/12/2021	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,847.61 FL	*2,847.61 FL
2	1		*TAILGATE LOWER SUPPORT PANEL	Repair	1,842.81 FL	*- FL
3	1		*TAILGATE HINGE	Not Necessary	757.24 FL	*- FL
4	1		*TAILGATE SIDE LOCK	O/S Dented	483.42 FL	*241.71 FL
5	1		*TAILGATE STOPPER RUBBER (2 PCS)	Cut	109.30 FL	*54.65 FL
6	1		*TAILGATE STOPPER BRACKET RH	Bent	182.71 FL	*182.71 FL
7	1		*SIDE GATE RH	Repair	3,847.10 FL	*- FL
8	1		*SIDE GATE LOWER LOCK RH	Not Necessary	274.32 FL	*- FL
9	6		*SIDE GATE HINGE	Not Necessary	1,135.86 FL	*- FL
10	1		*TAIL LAMP RH	Not Necessary	237.21 FL	*- FL
11	1		*TAIL LAMP SUPPORT BRACKET RH	Not Necessary	164.71 FL	*- FL
12	1		*REAR NUMBER PLATE LAMP	Not Necessary	124.05 FL	*- FL
13	1		*REAR CHASSIS CROSSMEMBER	Not Necessary	2,641.70 FL	*- FL
14	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
15	1		*TAIL GATE 60KM STICKER	Necessary	40.00 FS	*15.00 FS
16	1		*TAIL GATE 10 PAX STICKER	Necessary	40.00 FS	*15.00 FS
17	6		*CARGO BED U CLIP (SPECIAL TYPE)	Not Necessary	1,080.00 FS	*- FS
18	2		*REAR CARGO BED CHASSIS (SPECIAL TYPE)	Not Necessary	4,400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,258.04	3,356.68
- List Item Discount on L Items 25.00/25.00% (\$)	3,662.01	831.67
Total Parts (\$)	16,596.03	2,525.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,KNOCK ,WELD ,CUT ,ADJUST ,STRAIGHTEN ,GRAZE ,ALIGN	New	1,400.00	600.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,400.00	600.00
3	BULB CHECKING WIRING	New	180.00	30.00
4	TRANSFER TAILGATE MECHANISM	New	60.00	0.00
5	REMOVE AND REFIX REAR CARGO BED	New	1,800.00	0.00
6	REAR CHASSIS ALIGNMENT	New	250.00	0.00
7	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
			Gross Labour Cost (\$)	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >