

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012675/KGA3Q2**Date:** 09/06/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLT5028R**Insured Vehicle No :** SNA6132S

Date of Loss: 10/12/2021

Nature of Claim:

TP

Claim No: 9821412285SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLT5028R**

Make & Model: KIA CERATO K3, 1.6 (A)

Engine No: G4FGHH679243

Reg. Date: 31/10/2017 (Man. Year: 2017)

Chassis No: KNAFX411MJ5742059

Colour: Metallic Black

Odometer: 55006 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 4 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 4 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,589.50	1,969.20	620.30	23.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	770.00	940.00	54.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,299.50	2,739.20	1,560.30	36.29
+ GST 7.00/7.00% (S\$)	300.97	191.74	109.23	36.29
Nett Amount (S\$)	4,600.47	2,930.94	1,669.53	36.29
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,112.94		

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 15/12/2021 Inspected At:

Ah Lim Motor Company (AMK)

10 Ang Mo Kio Industrial Park 2A, #01-09 AMK

Autopoint

Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT EMBLEM	Not Necessary	37.00 FL	*- FL
2	1		*REAR BOOT LOGO	Not Necessary	35.00 FL	*- FL
3	1		*REAR BOOT LOCK	Repair	112.00 FL	*- FL
4	1		*REAR BOOT RUBBER	Serviceable	100.00 FL	*- FL
5	1		*REAR BUMPER	Buckled	668.00 FL	*668.00 FL
6	1		*REAR BUMPER REFLECTOR WITH LOWER GARNISH LH	Distorted / Cracked	347.00 FL	*347.00 FL
7	1		*REAR BUMPER SIDE RETAINER LH	Distorted	29.00 FL	*29.00 FL
8	12		*REAR BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Cracked	313.00 FL	*313.00 FL
10	2		*REAR BUMPER BRACKET UPPER LH & RH	Serviceable	10.00 FL	*- FL
11	2		*REAR BUMPER BRACKET LOWER CENTRE LH & RH	Serviceable	16.00 FL	*- FL
12	1		*TAILLAMP LH	Cut	788.00 FL	*788.00 FL
13	1		*REAR FENDER COWLING LH	Serviceable	75.00 FL	*- FL
14	8		*REAR FENDER COWLING CLIP	Not Necessary	24.00 FL	*- FL
15	1		*REAR END PANEL GARNISH	Serviceable	58.00 FL	*- FL
16	1		*TAILLAMP CLIP	Necessary	7.00 FL	*7.00 FL
17	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS
18	1		*BOOT LOGO K3 (NPA)	Not Necessary	0.00 FS	*- FS
19	1		*BOOT LOGO CC (NPA)	Not Necessary	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,855.00	2,188.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	265.50	218.80
Total Parts (\$\$)	2,589.50	1,969.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO REMOVE AND REINSTALL / REPLACE REAR BUMPER SENSORS	New	60.00	50.00
3	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
4	TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR BOOT, REAR END PANEL, REAR FENDER LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	700.00	300.00
5	TO SPRAY BOOT, REAR BUMPER, REAR END PANEL, REAR FENDER LH	New	850.00	400.00
Gross Labour Cost (\$\$)			1,710.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >