

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012676/BGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100317017
Claimant Vehicle No :	SGL228P	Insured Vehicle No :	SKG6776M
Date of Loss:	13/12/2021	Nature of Claim:	TP
		Claim No:	8715404082SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL228P		
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Engine No:	P520445391
Reg. Date:	27/06/2017 (Man. Year: 2017)	Chassis No:	JM6BN22A8H0153607
Colour:	Silver	Odometer:	39451 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,778.56	7,551.84	8,226.72	52.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,580.00	2,770.00	2,810.00	50.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,358.56	10,321.84	11,036.72	51.67
Approved Total (Overridden) (S\$)		8,250.00		
(S\$)	21,358.56	8,250.00	13,108.56	61.37
+ GST 7.00/7.00% (S\$)	1,495.10	577.50	917.60	61.37
Nett Amount (S\$)	22,853.66	8,827.50	14,026.16	61.37
+ Loss of Use (12.0 x S\$50.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,434.95		
Global Sum Settlement (S\$)		9,400.00		

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 14/12/2021 Inspected At:

Estimated Period of Repair: 9.0 days

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING
 AUTOCITY
 Singapore 575722

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Repair	1,592.30 FL	*- FL
2	1		*FRONT DOOR BLACK TAPE LH	Not Necessary	106.00 FL	*- FL
3	1		*REAR DOOR LH	Dented	1,485.00 FL	*1,000.00 FL
4	1		*REAR DOOR BLACK TAPE LH	Necessary	106.00 FL	*106.00 FL
5	1		*REAR DOOR OUTER HANDLE LH	Not Damaged	209.50 FL	*- FL
6	1		*REAR DOOR HANDLE INNER BRACKET LH	Not Damaged	344.20 FL	*- FL
7	1		*REAR DOOR WEATHERSTRIP LH	Torn	142.10 FL	*142.10 FL
8	1		*REAR DOOR REGULATOR ASSY LH	Broken	451.00 FL	*451.00 FL
9	1		*REAR DOOR REGULATOR MOTOR LH	Not Damaged	281.60 FL	*- FL
10	1		*REAR DOOR INNER LOCK LH	Jammed	528.90 FL	*180.00 FL
11	1		*REAR DOOR LOCK STRIKER LH	Not Damaged	86.50 FL	*- FL
12	2		*REAR DOOR HINGE LH	Not Damaged	164.00 FL	*- FL
13	1		*REAR DOOR CHECKER ARM LH	Not Damaged	102.80 FL	*- FL
14	1		*REAR DOOR TRIMBOARD LH	Broken	496.80 FL	*496.80 FL
15	1		*REAR DOOR FRAME RUBBER LH	Not Necessary	106.90 FL	*- FL
16	1		*DOOR CENTRE PILLAR LH	Not Damaged	872.00 FL	*- FL
17	1		*ROCKER PANEL LH	Dented	815.00 FL	*605.00 FL
18	1		*REAR FENDER LH	Dented	1,543.00 FL	*1,385.00 FL
19	1		*REAR FENDER INNER PANEL LH	Dented	1,125.80 FL	*635.00 FL
20	1		*REAR FENDER INNER COWLING LH	Not Damaged	363.60 FL	*- FL
21	1		*REAR FENDER INNER TRIM BOARD LH	Not Damaged	558.90 FL	*- FL
22	1		*REAR FENDER AIR VENT LH	Not Damaged	92.50 FL	*- FL
23	1		*REAR WINDSCREEN MOULDING	Necessary	231.00 FL	*98.00 FL
24	1		*REAR BUMPER	Cut	792.00 FL	*792.00 FL
25	1		*REAR BUMPER SIDE RETAINER	Necessary	168.00 FL	*45.00 FL
26	1		*REAR SHOCK ABSORBER LH	Bent	419.60 FL	*200.00 FL
27	1		*REAR LOWER ARM LH	Bent	594.50 FL	*255.00 FL
28	1		*REAR TRAILING ARM LH	Bent	489.60 FL	*397.00 FL
29	1		*REAR CONTROL ARM LH	Bent	497.50 FL	*296.30 FL
30	1		*REAR TRUST ARM LH	Bent	386.90 FL	*386.90 FL
31	1		*REAR ANTO ROLL BAR LINK LH	Not Damaged	168.90 FL	*- FL
32	1		*REAR KNUCKLE ARM LH	Dented	665.80 FL	*440.00 FL
33	1		*REAR KNUCKLE ARM BEARING LH	Jammed	435.00 FL	*341.20 FL
34	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
35	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS
36	1		*FRONT DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
37	1		*REAR DOOR SEALANT	Necessary	100.00 FS	*30.00 FS
38	1		*REAR DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
39	1		*REAR DOOR SPEAKER	Not Damaged	210.00 FS	*- FS
40	1		*ROCKER PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
41	1		*REAR FENDER SEALANT	Necessary	100.00 FS	*30.00 FS
42	1		*REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
44	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
45	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
46	1		*REAR WINDSCREEN PRIMER AND CLEANER	Not Necessary	60.00 FS	*- FS
47	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
48	1		*REAR ALLOY RIM LH	Cut	980.00 FS	*400.00 FS
49	1		*REAR TYRE LH	Cut	480.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,063.20	9,202.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,284.64	1,650.46
Total Parts (\$\$)	15,778.56	7,551.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT DOOR COMPONENT	New	150.00	0.00
2	R&R REAR DOOR COMPONENT	New	150.00	80.00
3	R&R REAR WINDSCREEN	New	250.00	120.00
4	R&R FUEL TANK PIPE	New	150.00	60.00
5	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
6	R&R REAR UNDER CARRIAGE	New	300.00	150.00
7	R&R REAR TYRE AND BALANCING	New	100.00	40.00
8	WHEEL ALIGNMENT	New	180.00	60.00
9	CHECK WIRING	New	100.00	0.00
10	UPHOLSTERY	New	300.00	0.00
11	PANEL BEATING	New	1,800.00	1,200.00
12	RUST PROOFING	New	200.00	0.00
13	SPRAY PAINTING	New	1,800.00	1,000.00
Gross Labour Cost (\$)			5,580.00	2,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >