



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2203840

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 20/06/2022
Reference CC4/FCI21012677/Aga3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBF 8498P

Insured Veh. GBK 3141A

Claim No. D21003431MFCV

Policy No.

Accident Date 11/12/2021

Inspection Date 14/02/2022

Description	Total
Survey Inspection	327.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	327.00
GST (7%)	22.89
Grand Total	349.89

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: CC4/FCI21012677/Aga3q2

Date: 20/06/2022

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBK 3141A	Veh. Inspected	GBF 8498P
Policy No.		Coverage (\$)	0.00
Claim No.	D21003431MFCV	Excess (\$)	0.00
Assign From	ESTHER	Assign Date	14/12/2021

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTFAT35Y60K207788	Colour	SILVER
Odometer	131064 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	MICHELIN	6 mm
L/H Front Tyre	195 R15C	MICHELIN	6 mm
R/H Rear Tyre	155 R12C	MICHELIN	6 mm
L/H Rear Tyre	155 R12C	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2021	Inspection Date	14/02/2022
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 8498P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	NOT NECESSARY	645.30	-
2	FRONT BUMPER BRACKET - LH & RH	NOT NECESSARY	380.40	-
1	FRONT GRILLE	CRACKED	517.50	517.50
1	FRONT GRILLE LOGO	NECESSARY	76.90	76.90
2	HEADLAMP - LH & RH	CRACKED	2,357.40	2,357.40
1	FRONT PANEL	DENTED	1,194.30	1,194.30
1	DYNA EMBLEM	NECESSARY	71.50	71.50
2	FRONT CORNER PANEL - LH & RH	TO REPAIR SEE LABOUR	596.00	-
1	FRONT WING MIRROR - LH (ROUND)	NOT NECESSARY	105.80	-
1	FRONT WING MIRROR STAY - LH	BROKEN	277.80	277.80
1	FRONT WINDSCREEN MOULDING	NECESSARY	278.20	278.20
1	AIRCON BLOWER	CRACKED	1,335.10	1,335.10
1	AIRCON SUCTION PIPE	DENTED	295.40	295.40
1	AIRCON DISCHARGE PIPE	DENTED	289.50	289.50
	LESS 25% DISCOUNT		-2,105.28	-1,673.40
			6,315.82	5,020.20
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	30.00	-
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	20.00	20.00
1	FRONT PANEL SEALANT (SN)	NECESSARY	60.00	60.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
			170.00	140.00
<u>LABOUR</u>				
	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL - LH & RH.		1,100.00	800.00
	TO PUTTY AND SPRAY UP PAINT WORKS.		1,000.00	700.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO SPRAY TUFFCOAT.		150.00	60.00
	TO REMOVE FRONT WINDSCREEN.		180.00	120.00

Report Ref No. CC4/FCI21012677/Aga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE DASHBOARD.		300.00	220.00
	TO REMOVE AIRCON SYSTEM & TOP UP AIRCON GAS.		200.00	120.00
			2,980.00	2,050.00
GRAND TOTAL			9,465.82	7,210.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,750.00

Report Ref No. CC4/FCI21012677/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 8498P

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 8498P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

