

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21012678/UPA3Q2**Date:** 29/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_02  
**Claimant Vehicle No :** SGX3775T **Insured Vehicle No :** GBG8479P  
 Date of Loss: 10/12/2021 Nature of Claim: TP Claim No: MFL2021D0005383

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGX3775T**  
 Make & Model: HONDA CR-V, 2.0 L AT (A) Engine No: R20A11704467  
 Reg. Date: 22/08/2007 (Man. Year: 2007) Chassis No: JHLRE28307C205486  
 Colour: Beige Odometer: 116656 km  
 Engine Capacity: 1997 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17 Rear Tyre Size: 225/65 R17  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,393.52	2,629.12	1,764.40	40.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,970.00	970.00	32.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,333.52</b>	<b>4,599.12</b>	<b>2,734.40</b>	<b>37.29</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>(S\$)</b>	7,333.52	3,500.00	3,833.52	52.27
<b>+ GST 7.00/7.00% (S\$)</b>	513.35	245.00	268.35	52.27
<b>Nett Amount (S\$)</b>	<b>7,846.87</b>	<b>3,745.00</b>	<b>4,101.87</b>	<b>52.27</b>
<b>+ Loss of Use (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,452.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,450.00</b>		

INSPECTION

Date of Assignment: 14/12/2021  
 Date Inspected: 15/12/2021 Inspected At: Progressive Car Care Pte Ltd (HQ)  
 Blk 3022A Ubi Road 1, #01-45/46  
 Singapore 408716  
 Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2022)
<b>Parts:</b> M1-SUV	HONDA CR-V 2.0 L AT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGX3775T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Badly Dented	1,106.40 FL	*1,106.40 FL
2	1		*FRONT DOOR RUBBER -RH	Not Necessary	94.50 FL	*- FL
3	1		*SET FRONT DOOR STICKER -RH	Necessary	35.00 FL	*35.00 FL
4	2		*FRONT DOOR HINGE-RH	Bent	88.40 FL	*88.40 FL
5	1		*FRONT DOOR REGULATOR GEAR W/MOTOR-RH	Damaged	470.70 FL	*470.70 FL
6	1		*FRONT DOOR OUTER MOULDING -RH	Bent	94.10 FL	*94.10 FL
7	1		*FRONT DOOR PROTECTOR -RH	Distorted	156.80 FL	*156.80 FL
8	1		*RHF MUDFLAP -RH	Distorted	44.30 FL	*44.30 FL
9	1		*ROCKER PANEL OUTER GARNISH /FRONT -RH	Distorted	1,290.70 FL	*1,290.70 FL
10	1		*SIDE MIRROR ASSY -RH	Repair	658.40 FL	*- FL
11	1		*REAR DOOR -R	Repair	1,077.60 FL	*- FL
12	1		*REAR DOOR PROTECTOR -LH	Serviceable	113.90 FL	*- FL
13	1		*REAR FENDER WHEEL ARCH GARNISH -LH	Serviceable	88.50 FL	*- FL
14	1		*REAR DOOR RUBBER -LH	Not Necessary	120.00 FL	*- FL
15	1		*SET REAR DOOR STICKER -RH	Not Necessary	52.60 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,491.90</b>	<b>3,286.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	1,098.38	657.28
<b>Total Parts (S\$)</b>	<b>4,393.52</b>	<b>2,629.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS	New	1,200.00	800.00
2	TO RESPRAY PAIINT ON ACCIDENT PORTIONS	New	1,400.00	1,000.00
3	TO TUFF -KOTE	New	30.00	30.00
4	TO CHECK WIRING	New	50.00	20.00
5	TO TRANSFER DOOR AND DOOR FITTING	New	160.00	60.00
6	TO 4 WHEEL ALIGNMENT	New	100.00	60.00
			<b>Gross Labour Cost (\$)</b>	<b>1,970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >