

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21012679/EGA3Q2**Date:** 08/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SFS1110M **Insured Vehicle No :** SLN5277U
 Date of Loss: 08/12/2021 Nature of Claim: TP Claim No: MFL2021D0005466

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFS1110M**
 Make & Model: HONDA ODYSSEY, 2.4 (A) Engine No: K24W72501253
 Reg. Date: 29/09/2020 (Man. Year: 2020) Chassis No: JHMRC1890LC202412
 Colour: White Odometer: 20383 km
 Engine Capacity: 2356 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
 Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,271.20	2,183.57	1,087.63	33.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,230.00	8,240.00	5,990.00	42.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,501.20	10,423.57	7,077.63	40.44
Approved Total (Overridden) (S\$)		9,783.57		
(S\$)	17,501.20	9,783.57	7,717.63	44.10
+ GST 7.00/7.00% (S\$)	1,225.08	684.85	540.23	44.10
Nett Amount (S\$)	18,726.28	10,468.42	8,257.86	44.10
+ Car Rental (7.0 x S\$150.00/day + 7.00% GST) (S\$)		1,123.50		
Nett Liability (S\$)		11,591.92		

INSPECTION

Date of Assignment: 15/12/2021
 Date Inspected: 17/12/2021 Inspected At: Kah Motor Co Sdn Bhd (alexandra) (HQ)
 255 Alexandra Road
 Singapore 159937
 Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Feb 2022)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFS1110M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY ,RR BUMPER	Dented	428.32 FS	*428.32 FS
2	1		*REFLECTOR ASSY.RR	Not Necessary	36.30 FS	*- FS
3	1		*SPOILER ASSY ,R.RR	Crushed	74.40 FS	*74.40 FS
4	1		*SPACERR.RR.BUMPER SIDE	Not Necessary	15.30 FS	*- FS
5	1		*SPACERL.RR.BUMPER SIDE	Broken	15.30 FS	*15.30 FS
6	1		*CLIP, BUMPER (8 PCS)	Necessary	13.80 FS	*13.80 FS
7	1		*TAILGATE COMP	Dented	856.42 FS	*856.42 FS
8	1		*WEATHERSTRIPTAILGATE	Torn	93.90 FS	*93.90 FS
9	1		*LIGHT ASSY ,R.LID	Not Necessary	308.85 FS	*- FS
10	1		*LIGHT ASSY ,R,TAIL	Not Necessary	670.35 FS	*- FS
11	1		*PANEL COMP REAR	Dented	368.55 FS	*368.55 FS
12	1		*CAPPIVOT	Necessary	3.90 FS	*3.90 FS
13	1		*RUBBER AWINDSHIELD DAM	Necessary	2.92 FS	*2.92 FS
14	2		*DAMPERSTD 5X5	Necessary (1 PCS ONLY)	13.65 FS	*6.82 FS
15	4		*SPACERRR.W/SHIELD	Necessary	12.60 FS	*12.60 FS
16	1		*MOLDINGL .RR.WINDSHIELD CORNER	Necessary	13.50 FS	*13.50 FS
17	1		*MOLDINGR.RR.WINDSHIELD CORNER	Necessary	13.50 FS	*13.50 FS
18	2		*MOULDINGRR.WINDSHIELD SIDE	Necessary	28.80 FS	*28.80 FS
19	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
20	1		*EMBLEMH	Necessary	21.07 FS	*21.07 FS
21	1		*EMBLEM,RR	Necessary	24.82 FS	*24.82 FS
22	1		*MOLDING ASSYRR.LICENSE GARN	Broken	140.40 FS	*140.40 FS
23	6		*CLIPTAILGATE SPOILER	Necessary	11.70 FS	*11.70 FS
24	1		*STOPPERTAILGATE	Necessary	2.85 FS	*2.85 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **3,271.20** **2,183.57**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY JOINT SEALANT FOR END PANEL	New	150.00	120.00
2	WINDSCREEN SEALANT	New	150.00	150.00
3	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	380.00	280.00
4	REMOVE & RENEW REVERSE SENSORS	New	380.00	280.00
5	RESET VEHICLE SMART ENTRY SYSTEM	New	800.00	650.00
6	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	800.00	650.00
7	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	800.00	650.00
8	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	800.00	650.00
9	REMOVE & INSTALL RR WINDSCREEN	New	650.00	650.00
10	CUT OFF & RENEW RR PANEL RENEW ALL DAMAGE PARTS	New	4,000.00	1,300.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,500.00	1,040.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	520.00	520.00
13	CUT OFF & RENEW RR PANEL STRAIGHTEN ALIGN FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	New	1,300.00	1,300.00
Gross Labour Cost (\$\$)			14,230.00	8,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >