

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21012680/VTF3E2

Date: 29/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMW7583M

Insured Vehicle No : SDU5188B

Date of Loss: 12/12/2021

Nature of Claim: TP

Claim No: 0531536905SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW7583M**

Make & Model: TOYOTA PRIUS, 1.5 (A)

Engine No: 2ZR2H38923

Reg. Date: 09/12/2020 (Man. Year: 2020)

Chassis No: JTDZS3EU90J060593

Colour: Silver

Odometer: 116394 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Arivo 5 mm

Rear Left Side: Arivo 5 mm

Front Right Side: Arivo 5 mm

Rear Right Side: Arivo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/12/2021

Date Inspected: 16/12/2021 Inspected At:

A-Tec Automotive Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #04-20 Premier
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$109,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	Necessary	0.00 F	*- F
4	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SPONGE	Cut	0.00 F	*- F
6	1		*FRT RH BUMPER DAY RUNNING LIGHT	Cracked	0.00 F	*- F
7	1		*FRT RH BUMPER FOG LAMP	Serviceable	0.00 F	*- F
8	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
9	1		*FRT RH WHEEL RIM	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >