

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012681/VEA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800125272
Claimant Vehicle No :	SHD1642A	Insured Vehicle No :	SMF1804E
Date of Loss:	14/12/2021	Nature of Claim:	TP
		Claim No:	6315710688SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1642A	Engine No:	G4LEJU156604
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU129629
Reg. Date:	26/02/2019 (Man. Year: 2018)	Odometer:	247784 km
Colour:	Silver		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,590.80	48.00	1,542.80	96.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	740.00	1,090.00	59.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,420.80	788.00	2,632.80	76.96
+ GST 7.00/7.00% (S\$)	239.46	55.16	184.30	76.96
Nett Amount (S\$)	3,660.26	843.16	2,817.10	76.96
+ Loss of Use (3.0 x S\$40.00/day) (S\$)		120.00		
+ Car Rental (3.0 x S\$72.76/day) (S\$)		218.28		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,183.44		
Global Sum Settlement (S\$)		1,180.00		

INSPECTION

Date of Assignment:	15/12/2021	
Date Inspected:	15/12/2021	Inspected At: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	2.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	294.80 FL	*- FL
3	2		*REAR BUMPER REINFORCEMENT N/S & O/S LOWER BRACKET	Repair	20.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT CENTRE LOWER BRACKET	Repair	15.00 FL	*- FL
5	2		*REAR BUMPER N/S & O/S STAY	Repair	276.20 FL	*- FL
6	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Repair	66.20 FL	*- FL
7	1		*REAR BUMPER LOWER MOULDING CENTRE	Repair	216.50 FL	*- FL
8	1		*REAR BUMPER LOWER COVER	Repair	47.50 FL	*- FL
9	1		*REAR BUMPER CAP HOOK	Repair	9.10 FL	*- FL
10	2		*REAR BUMPER N/S & O/S REFLECTOR	Repair	63.80 FL	*- FL
11	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
12	1		*SET REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
13	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	38.00 FS	*- FS
14	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,884.50	48.00
- List Item Discount on L Items 20.00/20.00% (S\$)	293.70	0.00
Total Parts (S\$)	1,590.80	48.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	0.00
3	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ETC TO FACILITATE REPAIRS	New	180.00	180.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE END PANEL	New	600.00	180.00
5	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,END PANEL,REAR BUMPER MOULDING (BLACK) ,REAR BUMPER LOWER COVER (BLUE)	New	800.00	330.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	20.00
Gross Labour Cost (S\$)			1,830.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >