

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012682/RQCE2

Date: 29/06/2022

REFERENCE

Insured/Claimant: CHANDY KUSUMA Policy No: 1900085534
Date of Loss: 10/12/2021 Nature of Claim: OD Claim No: 5322660858SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML277B**
Make & Model: AUDI RS5 COUPE, 2.9 TFSI QU TIP (SR) (A) Engine No: DEC014654
Reg. Date: 17/04/2019 (Man. Year: 2019) Chassis No: WUAZZZF46KA900543
Colour: Grey Odometer: 10057 km
Engine Capacity: 2894 cc
Market Value/New Car Price: S\$347,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/30ZR20 Rear Tyre Size: 275/30ZR20
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	67,263.00	36,164.40	31,098.60	46.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,924.00	9,124.00	7,800.00	46.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	84,187.00	45,288.40	38,898.60	46.20
- Excess (S\$)	2,500.00	2,500.00	0.00	0.00
(S\$)	81,687.00	42,788.40	38,898.60	47.62
+ GST 7.00/7.00% (S\$)	5,718.09	2,995.19	2,722.90	47.62
Nett Amount (S\$)	87,405.09	45,783.59	41,621.50	47.62

INSPECTION

Date of Assignment: 15/12/2021
Date Inspected: 14/12/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	5,937.00 FS	*4,749.60 FS
2	1		*FRONT BUMPER SECURING STRIP	Not Necessary	53.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP INNER	Not Necessary	36.00 FS	*- FS
4	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	334.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER (BLACK)	Not Necessary	613.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	722.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	350.00 FS	*- FS
8	1		*FRONT BUMPER LOWER SPOILER TRIM	Not Necessary	708.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER - LOWER	Not Necessary	856.00 FS	*- FS
10	1		*FRONT BUMPER SPOILER - LH	Not Necessary	676.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	736.00 FS	*- FS
12	1		*FRONT AIR GUIDE INNER - LH	Not Necessary	75.00 FS	*- FS
13	2		*FRONT AIR GUIDE - LH / RH	Not Necessary	452.00 FS	*- FS
14	1		*RADIATOR GRILLE	Cracked	4,172.00 FS	*3,337.60 FS
15	1		*RS4 EMBLEM	Necessary	128.00 FS	*102.00 FS
16	1		*RADIATOR GRILLE CAP	Missing	211.00 FS	*168.80 FS
17	2		*FRONT PARKING AID SENSOR SUPPORT - LH / RH	Not Necessary	102.00 FS	*- FS
18	1		*RADIATOR GRILLE UPPER COVER	Not Necessary	155.00 FS	*- FS
19	1		*RADIATOR GRILLE LOWER COVER	Cracked	213.00 FS	*170.40 FS
20	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	845.00 FS	*675.60 FS
21	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	297.00 FS	*237.60 FS
22	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	134.00 FS	*- FS
23	1		*FRONT BUMPER BRACKET - LH	Cracked	228.00 FS	*182.00 FS
24	1		*FRONT BUMPER TOP COVER	Deformed	242.00 FS	*193.60 FS
25	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
26	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
27	1		*FRONT LOCK CARRIER BRACKET	Bent	244.00 FS	*195.20 FS
28	2		*FRONT BUMPER SUPPORT - LH / RH	Cracked / Necessary	58.00 FS	*44.96 FS
29	4		*POP RIVET	Necessary	4.00 FS	*2.56 FS
30	1		*HORN - LH	Not Necessary	201.00 FS	*- FS
31	1		*HORN SUPPORT - LH	Not Necessary	50.00 FS	*- FS
32	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	0.00 FS	*- FS
33	4		*FRONT PARKING AID SENSOR SEAL RING	Necessary	9.00 FS	*7.28 FS
34	1		*SET FRONT BUMPER WIRING	Not Necessary	510.00 FS	*- FS
35	1		*LICENCE PLATE SUPPORT	Cut	621.00 FS	*496.80 FS
36	1		*FRONT FENDER - LH	Bent	5,665.00 FS	*4,532.00 FS
37	3		*POP RIVET	Necessary	10.00 FS	*7.92 FS
38	1		*FRONT FENDER CLOSING ELEMENT - LH	Necessary	72.00 FS	*57.52 FS
39	1		*FRONT FENDER BRACKET - LH	Bent	35.00 FS	*27.92 FS
40	1		*FRONT FENDER RETAINER - LH	Not Necessary	49.00 FS	*- FS
41	1		*FRONT FENDER TRIM - LH	Deformed	402.00 FS	*321.60 FS
42	1		*FRONT FENDER ADAPTER - LH	Not Necessary	86.00 FS	*- FS
43	1		*FRONT FENDER BRACE - LH	Not Necessary	118.00 FS	*- FS
44	1		*FRONT FENDER BRACKET CENTER - LH	Not Necessary	49.00 FS	*- FS
45	1		*FRONT FENDER BRACKET BACK - LH	Not Necessary	32.00 FS	*- FS
46	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	33.00 FS	*- FS
47	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	296.00 FS	*- FS
48	1		*FRONT BACK PANEL COVER - LH	Not Necessary	26.00 FS	*- FS
49	1		*FRONT WHEEL SPOILER	Not Necessary	264.00 FS	*- FS
50	1		*FRONT SPOILER - LH	Not Necessary	35.00 FS	*- FS
51	1		*STONE CHIP GUARD - LH	Not Necessary	51.00 FS	*- FS
52	1		*FRONT FENDER FLEDGE COVER LONG - LH	Necessary	31.00 FS	*24.64 FS
53	1		*FRONT FENDER FLEDGE COVER SHORT - LH	Necessary	23.00 FS	*17.92 FS
54	1		*BONNET	Bent	3,246.00 FS	*2,596.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	2		*BONNET HINGE - LH / RH	Bent	610.00 FS	*487.20 FS
56	1		*BONNET IMPACT PROTECTION - CENTER / LH / RH (3PCS)	Necessary	84.00 FS	*65.68 FS
57	2		*BONNET GAS FILLED	Not Necessary	241.00 FS	*- FS
58	1		*BONNET SOUND ABSORBER	Not Necessary	343.00 FS	*- FS
59	1		*BONNET SOUND ABSORBER OUTER	Necessary	215.00 FS	*171.60 FS
60	1		*BONNET STRIKER - LH / RH	N/S Bent	100.00 FS	*39.92 FS
61	1		*BONNET LOCK	N/S Bent	427.00 FS	*170.80 FS
62	2		*CONNECTOR HOUSING	Not Necessary	26.00 FS	*- FS
63	2		*CONNECTOR HOUSING BRAKET	Not Necessary	19.00 FS	*- FS
64	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	58.00 FS	*- FS
65	1		*BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
66	1		*BONNET BOWDEN CABLE - OUTER	Cut	58.00 FS	*46.00 FS
67	1		*BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
68	1		*BONNET LOCK CABLE	Not Necessary	74.00 FS	*- FS
69	1		*PLENUM CHAMBER	Not Necessary	97.00 FS	*- FS
70	1		*HEADLIGHT MATRIX BEAM - LH	Cracked	13,044.00 FS	*10,435.20 FS
71	1		*HEADLIGHT POWER MODULE	Not Necessary	1,206.00 FS	*- FS
72	1		*HEADLIGHT CONTROL UNIT	Not Necessary	751.00 FS	*- FS
73	1		*HEADLIGHT HOSE	Not Necessary	36.00 FS	*- FS
74	3		*SPACER	Not Necessary	122.00 FS	*- FS
75	1		*LIFT CYLINDER - LH	Not Necessary	210.00 FS	*- FS
76	1		*LIFT CYLINDER BRACKET	Not Necessary	6.00 FS	*- FS
77	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	93.00 FS	*- FS
78	1		*FRONT LOCK CARRIER	Cracked	1,332.00 FS	*1,065.60 FS
79	2		*RADIATOR COOLANT SUPPORT	Bent	76.00 FS	*30.32 FS
80	1		*AIRCOND CONDENSER	Bent	622.00 FS	*497.60 FS
81	1		*HIGH PRESSURE VALVE	Not Necessary	51.00 FS	*- FS
82	1		*A/C PRESSURE SENSOR	Not Working	186.00 FS	*148.80 FS
83	1		*REFRIGERANT LINE - SUCTION	Not Necessary	167.00 FS	*- FS
84	1		*REFRIGERANT LINE - PRESSURE HOSE	Not Necessary	340.00 FS	*- FS
85	1		*REFRIGERANT LINE - SUCTION FRONT	Not Necessary	248.00 FS	*- FS
86	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Bent	19.00 FS	*14.56 FS
87	1		*AIR COOLER CHARGED	Bent	1,340.00 FS	*1,072.00 FS
88	1		*RADIATOR COOLANT COOLER	Bent	1,190.00 FS	*952.00 FS
89	1		*RADIATOR ADDITIONAL COOLER - CENTER	Not Necessary	2,724.00 FS	*- FS
90	1		*RADIATOR ADDITIONAL COOLER - SUPERCOOLING LEVEL	Not Necessary	2,545.00 FS	*- FS
91	1		*RADIATOR AIR GUIDE	Not Necessary	42.00 FS	*- FS
92	2		*RADIATOR RUBBER BUSH LOWER INSULATOR	Not Necessary	18.00 FS	*- FS
93	2		*RADIATOR RUBBER BUSH MOUNTING LOWER	Not Necessary	25.00 FS	*- FS
94	1		*RADIATOR FAN RING	Cracked	306.00 FS	*244.80 FS
95	2		*RADIATOR FAN CONTROL UNIT - LH / RH	Not Necessary	3,018.00 FS	*- FS
96	2		*RADIATOR AIR GUIDE LH - INNER / OUTER	Cracked	93.00 FS	*73.44 FS
97	1		*RADIATOR AIR GUIDE RH - INNER / OUTER	Outer Cracked	93.00 FS	*24.32 FS
98	1		*RADIATOR AIR GUIDE - LOWER FRONT	Not Necessary	46.00 FS	*- FS
99	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	38.00 FS	*- FS
100	1		*RADIATOR AIR GUIDE - RH	Not Necessary	109.00 FS	*- FS
101	1		*RADIATOR COOLANT (6PCS)	Necessary	266.00 FS	*212.64 FS
102	1		*RADIATOR INTAKE AIR DUCT - RH	Not Necessary	22.00 FS	*- FS
103	1		*RADIATOR INTAKE AIR GUIDE HOSE	Not Necessary	53.00 FS	*- FS
104	1		*RADIATOR INTAKE HOSE	Not Necessary	113.00 FS	*- FS
105	2		*FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH	Cut	1,282.00 FS	*1,024.00 FS
106	2		*FRONT WINDOW GUIDE TRIM STRIP - LH / RH	Not Necessary	594.00 FS	*- FS
107	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
108	1		*SUNDRIES	Necessary	500.00 FS	*53.84 FS
109	1		*FLAT CONTACT HOUSING (Supplementary)	Necessary	16.00 FS	*12.80 FS
110	1		*PRESSURE PIPE (Supplementary)	Bent	1,368.00 FS	*1,094.40 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

F=Franchise part. S=SpcNett.

					Total Parts (S\$)	67,263.00	36,164.40
--	--	--	--	--	--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,700.00	1,700.00
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS	New	560.00	560.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO REPAIR BOTH FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	3,000.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, LHS FRONT FENDER, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS	New	7,000.00	2,750.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
			Gross Labour Cost (S\$)	16,924.00
				9,124.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >