

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21012686/TQCN2**Date:** 25/03/2022**REFERENCE**

Insured/Claimant:	LAU WAI LING (LIU HUILING)	Policy No:	2100487436-05
Date of Loss:	08/11/2021	Nature of Claim:	OD
		Claim No:	7635337539SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLH1645Z</b>		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A)	Engine No:	CZC551159
Reg. Date:	26/10/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8V8G1095491
Colour:	Silver	Odometer:	36998 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$67,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,233.00	3,583.20	4,649.80	56.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,402.00	4,552.00	2,850.00	38.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,635.00</b>	<b>8,135.20</b>	<b>7,499.80</b>	<b>47.97</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,094.45</b>	<b>569.46</b>	<b>524.99</b>	<b>47.97</b>
<b>Nett Amount (S\$)</b>	<b>16,729.45</b>	<b>8,704.66</b>	<b>8,024.79</b>	<b>47.97</b>

**INSPECTION**

Date of Assignment:	15/12/2021		
Date Inspected:	14/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,070.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	32.00 FS	*- FS
4	1		*REAR LIGHT REFLECTOR-RH	Not Necessary	41.00 FS	*- FS
5	1		*REAR BUMPER GUIDE SECTION INNER-RH	Not Necessary	67.00 FS	*- FS
6	1		*REAR WHEEL HOUSING LINER-RH	Not Necessary	240.00 FS	*- FS
7	1		*REAR SILL PANEL ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
8	1		*REAR WHEEL SPOILER-RH	Not Necessary	35.00 FS	*- FS
9	1		*REAR DOOR-RH	Bent	3,039.00 FS	*2,431.20 FS
10	1		*REAR DOOR SEAL-RH	Necessary	161.00 FS	*128.40 FS
11	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
12	1		*CLEANER SOLUTION	Not Necessary	68.00 FS	*- FS
13	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	129.00 FS	*- FS
14	1		*REAR DOOR CATCH-RH	Distorted	94.00 FS	*74.80 FS
15	1		*REAR ALUMINIUM RIM	Cut	1,166.00 FS	*932.80 FS
16	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
17	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
18	1		*SUNDRIES	Necessary	300.00 FS	*16.00 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (S\$)</b>	<b>8,233.00 3,583.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	350.00	350.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR.TO REPAIR RHS REAR FENDER AND RHS SILL PANEL.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
4	TO RESPRAY REAR BUMPER,RHS REAR FENDER,RHS REAR DOOR AND RHS SILL PANEL	New	3,500.00	2,200.00
5	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,402.00</b>	<b>4,552.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >