

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21012687/Bty3e2	
	8 SHENTON WAY AXA TOWERSING		Date	11/01/2022	
	ATTN: ONG KIAN	THENG DERICK	Code	: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMA 6368R	Veh. Inspected	FBS 5002M	
	Policy No.	GA536258	Coverage (\$)	0.00	
	Claim No.	S1M03NTX	Excess (\$)	0.00	
	Assign From	ONG KIAN THENG DERICK	Assign Date	15/12/2021	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA AEROX155	c.c	155	
	Engine No.	HIDDEN	Year of Reg.	2021	
	Chassis No.	MH3SG6420MJ008345	Colour	BLACK	
	Odometer	19612 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	110/80/14	IRC	6 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	140/70/14	CONTINENTAL	6 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.				
5.	5. General Information				
	Accident Date	06/12/2021	Inspect Date / Time	15/12/2021 (02:23 PM)	
	Survey held at	MS CAR AUTO PTE LTD			
		8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21012687/Bty3e2

Inspected By

LIM TEOW GUAN

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser