

NS/INC21012692/T1tc

ASS. REC. BY: Tan JH

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. **MT/1154478 -002**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: Suman

Veh No: SMC 7442B Yr Regn: 20/7/ Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 cc 1685

Colour: yellow A/C: Insured / Std / NI / NA

Sp. Reading: 43135 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MM HLB4149M4100078

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 13/12/21

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COR I/s \$3500 , 3 days.

RED: 3374.64;49%

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B.H. (F) _____

Days Of Repair: **3**

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 13.12.2021
Time: 15:30:52
Page: 1

Jumani

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305497815
REGN NO : SHC7442B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 15.12.2017
DATE/TIME IN : 11.12.2021 19:00
ACCIDENT DATE : 11.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A BUMPER FRT COVER+
0002 04-01-0103-0782-A LAMP ASSY-HEAD RH#
0003 04-01-0103-0573-A PANEL-FENDER RH+
0004 04-01-0103-0640-G BRACKET-FR BUMPER SIDE RH
0005 04-01-0103-0641-G CARRIER ASSY-FR END MODUL
0006 04-01-0103-0572-G PANEL ASSY-HOOD#
0007 04-01-0101-0111-G BUMPER COVER CLIP

1 1,052.20 20.00 841.76 de
1 1,388.00 20.00 1,110.40 car
1 663.00 20.00 530.40 de
1 44.80 20.00 35.84 de
1 907.40 20.00 725.92 car
1 2,265.90 20.00 1,812.72 X
10 22.00 20.00 17.60 car

SUB-TOTAL : 5,074.64

JOB NATURE

0000 PB PANEL BEATING
0001 SP SPRAYPAINT CHARGE
0002 17-01 CHECK ALL LIGHTING
0003 20-00 TUFF COAT ON AFFECTED PARTS.

900.00 500
800.00 500
50.00 30
50.00 30

Tanfiah 97495747
WP 13/12/21 430pm
LBS Nsm after repair
Tanfiah C. Chantawan
03 days

Date/Time: 13.12.2021 15:18

Page : 1

am: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4150707

JC NO305497815

OMER

IS CITYCAB PTE LTD
 OMER NO. 7010070
 ESS 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 (R) 65551188 (O)
 (P)

DUNT CARD NO.

REGN NO.:

SHC7442B

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

11.12.2021 19:00

YR OF MANU.

15.12.2017

TARGET DATE

CHASSIS CODE

KMHLB41UMHU100078

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 11.12.2021
 Accure: 3P.11.12.2021

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHC7442B

JU NTUC

Vehicle No.:

SHC7442B

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard