

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG21012694/KQF3E2**Date:** 03/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210032440
<b>Claimant Vehicle No :</b>	SMH1676Y	<b>Insured Vehicle No :</b>	SKA9800M
Date of Loss:	10/12/2021	Nature of Claim:	TP
		Claim No:	3885587035SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMH1676Y</b>	Engine No:	P520559336
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BN24A8K0258679
Reg. Date:	14/01/2019 (Man. Year: 2018)	Odometer:	40035 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	15/12/2021	
Date Inspected:	15/12/2021	Inspected At: Kum Chew Motor Workshop (HQ) 160 Sin Ming Drive #05-08 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$92,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR ASSY	Bent	0.00 F	*- F
2	1		*REAR DOOR ASSY	Bent	0.00 F	*- F
3	1		*FRT DOOR BOARD	Mtg Cracked	0.00 F	*- F
					<b>Total Parts (\$\$)</b>	<b>0.00 0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >