



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7772J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT BUMPER COVER	TO REPAIR SEE LABOUR	430.90	-
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER SIDE BRACKET LH	NOT NECESSARY	28.00	-
1	HEADLAMP LH	CUT	1,993.65	1,993.65
1	DAY LIGHT LH	NOT NECESSARY	642.50	-
1	FRT BUMPER SIDE MOULDING LH	DEFORMED	186.90	186.90
1	FRT FENDER LH	TO REPAIR SEE LABOUR	588.80	-
1	EMBLEM-BLUE DRIVE LH	NECESSARY	26.60	26.60
1	FRT WHEEL HUB CAP LH	DEFORMED	346.40	346.40
	LESS 20% DISCOUNT		-853.15	-515.11
			3,412.60	2,060.44
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRT TYRE LH (SN)	NOT NECESSARY	216.00	-
			216.00	-
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT BUMPER COVER AND FRT FENDER LH.		1,050.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	CHECK ALL LIGHTING.		60.00	30.00
			1,770.00	1,055.00
	<b>GRAND TOTAL</b>		<b>5,398.60</b>	<b>3,115.44</b>

<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>3,115.44</b>
--	--	--	-----------------

Report Ref No. NS/INC21012697/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.