

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012699/EVF3N2**Date:** 11/01/2022**REFERENCE**

Insured/Claimant: SEEM KOK SENG Policy No: 1700091333
Date of Loss: 14/12/2021 Nature of Claim: OD Claim No: 8125285374SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV3579U**
Make & Model: KIA CARENS, 1.7 (A) Engine No: D4FDHH546890
Reg. Date: 28/12/2017 (Man. Year: 2017) Chassis No: KNAHU815VJ7193822
Colour: Silver Odometer: 115302 km
Engine Capacity: 1685 cc
Market Value/New Car Price: S\$70,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55ZR16 Rear Tyre Size: 205/55ZR16
Front Left Side: Hankook 4 mm Rear Left Side: Hankook 4 mm
Front Right Side: Hankook 4 mm Rear Right Side: Hankook 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,638.40	3,112.80	1,525.60	32.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,934.00	3,360.00	1,574.00	31.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,572.40	6,472.80	3,099.60	32.38
+ GST 7.00/7.00% (S\$)	670.07	453.10	216.97	32.38
Nett Amount (S\$)	10,242.47	6,925.90	3,316.57	32.38

INSPECTION

Date of Assignment: 15/12/2021
Date Inspected: 16/12/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-REAR COMBINATION,RH	Cut	357.00 FL	*357.00 FL
2	1		*PANEL ASSY-TAIL GATE	Dented	1,218.00 FL	*1,218.00 FL
3	1		*TRIM-TRANSVERSE RR	Not Necessary	71.00 FL	*- FL
4	1		*LATCH ASSY-TAIL GATE	Not Necessary	109.00 FL	*- FL
5	1		*EMBLEM-CARENS	Necessary	36.00 FL	*36.00 FL
6	1		*EMBLEM-CRDI	Necessary	29.00 FL	*29.00 FL
7	1		*GLASS ASSY-TAIL GATE	Not Necessary	490.00 FL	*- FL
8	2		*STOPPER-RR WINDOW GLASS	Necessary	30.00 FL	*15.00 FL
9	6		*PAD-WINDSHIELD GLASS	Not Necessary	12.00 FL	-
10	1		*GROMMET-REAR WIPER	Necessary	5.00 FL	*5.00 FL
11	1		*ORNAMENT-KIA	Necessary	76.00 FL	*76.00 FL
12	1		*GARNISH-TAIL GATE,UPR	Not Necessary	135.00 FL	*- FL
13	1		*COVER-RR BUMPER,UPR	Broken	576.00 FL	*576.00 FL
14	1		*COVER-RR BUMPER,LWR	Broken	211.00 FL	*211.00 FL
15	1		*BRACKET-RR BUMPER SIDE LWR,RH	Not Necessary	21.00 FL	*- FL
16	1		*W/STRIP-TAIL GATE OPNG	Not Necessary	131.00 FL	*- FL
17	1		*LAMP ASSY-REAR FOG,RH	Broken	116.00 FL	*116.00 FL
18	1		*BRACKET-FR BUMPER SIDE,RH	Not Necessary	4.00 FL	*- FL
19	1		*WIRING HARNESS-R.P.A.S	Not Necessary	251.00 FL	*- FL
20	1		*BRACKET-RR BUMPER RAIL,UPR	Broken	5.00 FL	*5.00 FL
21	1		*BRACKET-RR BUMPER RAIL,LWR	Not Necessary	5.00 FL	*- FL
22	1		*BRACKET-RR BUMPER LWR,CTR	Not Necessary	5.00 FL	*- FL
23	1		*BRACKET-RR BUMPER RAIL,LWR	Not Necessary	5.00 FL	*- FL
24	1		*BEAM-RR BUMPER	Broken	367.00 FL	*367.00 FL
25	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	79.00 FL	*- FL
26	1		*STAY-RR BUMPER LH	Not Necessary	159.00 FL	*- FL
27	1		*STAY-RR BUMPER RH	Bent	159.00 FL	*159.00 FL
28	1		*BRACKET ASSY-RR BUMPER SIDE,LH	Not Necessary	25.00 FL	*- FL
29	1		*BRACKET ASSY-RR BUMPER SIDE,RH	Not Necessary	25.00 FL	*- FL
30	2		*HOLDER-BACK WARING SYSTEM OTR	Not Necessary	8.00 FL	*- FL
31	2		*HOLDER-BACK WARING SYSTEM INR	Not Necessary	8.00 FL	*- FL
32	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	162.00 FL	*- FL
33	1		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	162.00 FL	*- FL
34	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
35	1		*C&C EMBLEM	Necessary	40.00 FS	*40.00 FS
36	1		*CROSSMEMBER ASSY-RR END (Supplementary)	Dented	453.00 FL	*453.00 FL
37	10		*CLIPS (Supplementary)	Necessary	10.00 FL	*10.00 FL
38	1		*SKID PLATE-RR BUMPER (Supplementary)	Broken	179.00 FL	*179.00 FL
39	1		*CAP-RR HOOK (Supplementary)	Missing	4.00 FL	*4.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,778.00	3,876.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,139.60	763.20
Total Parts (\$\$)	4,638.40	3,112.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, TAILGATE, END PANEL & AFFECTED AREA. REPAIR ON REAR RH FENDER	New	2,000.00	1,000.00
2	PAINT WORK ON REAR BUMPER, TAILGATE, END PANEL & REAR RH FENDER	New	1,400.00	1,050.00
3	REMOVE & REPLACE REAR PARKING ASSITS FOR FACILITIES REPAIR	New	80.00	80.00
4	REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR	New	240.00	240.00
5	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
6	TO TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL	New	192.00	120.00
7	TO REMOVE & INSTALL REAR COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
8	TO PERFORM RUST PREVENTION	New	120.00	40.00
9	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	80.00
10	TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
11	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	192.00	120.00
12	REPLACE REAR END PANEL (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			4,934.00	3,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >