



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Seem Kok Seng
	Reg No/Reg Date	SLV3579U / 28/12/201
	Date In/Mileage	16/12/2021/ 0
	Chassis No	KNAHU815VJ7193822
	Engine No	D4FDHH546890
	Make/Model	KIA/CARENS 1.7 A D EX FL DY7
	Colour/Trim	IM TITANIUM SILVER/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
LAX00000	Credit	15/12/2021/ 11:42	BLK	282 / Kevin Leong	43990				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	REPLACE REAR BUMPER, TAILGATE, END PANEL & AFFECTED AREA REPAIR ON REAR RH FENDER								2000.00
E PNT98000	PAINT WORK ON REAR BUMPER, TAILGATE, END PANEL & REAR RH FENDER								1400.00
E PNT88000	REMOVE & RELACE REAR PARKING ASSITS FOR FACILITIES REPAIR								80.00
E PNT88000	REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR								240.00
M SUNDRY	TO APPLY WINDSCREE SEALANT								80.00
E PNT88000	TO TRANSFER REAR BOOT ATTACHEMENTS TO NEW PANEL								192.00
E PNT88000	TO REMOVE & INSTALL REAR COMPARTMENT FOR FACILITATE REPAIR								120.00
M SUNDRY	TO PERFORM RUST PREVENTION								120.00
M SUNDRY	TO APPLY SEALANT ON AFFECTED AREA								80.00
A 54900099	TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								192.00
M SUNDRY	TO SUPPLY C&C EMBLEM								40.00
M SUNDRY	SUNDRIES								40.00
M LAMP ASSY-REAR COMBINATION,RH					1.00	357.00	20.00	285.60	
M PANEL ASSY-TAIL GATE					1.00	1218.00	20.00	974.40	
M TRIM-TRANSVERSE RR					1.00	71.00	20.00	56.80	
M W/STRIP-TAIL GATE OPNG					1.00	131.00	20.00	104.80	
M LATCH ASSY-TAIL GATE					1.00	109.00	20.00	87.20	
M EMBLEM-CARENS					1.00	36.00	20.00	28.80	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Seem Kok Seng
	Reg No/Reg Date	SLV3579U / 28/12/201
	Date In/Mileage	16/12/2021/ 0
	Chassis No	KNAHU815VJ7193822
	Engine No	D4FDHH546890
	Make/Model	KIA/CARENS 1.7 A D EX FL DY7
	Colour/Trim	IM TITANIUM SILVER/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/12/2021/ 11:42	BLK	282 / Kevin Leong	43990

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M EMBLEM-CRDI	1.00	29.00	20.00	23.20
M GLASS ASSY-TAIL GATE	1.00	490.00	20.00	392.00
M STOPPER-RR WINDOW GLASS	2.00	15.00	20.00	24.00
M PAD-WINDSHIELD GLASS	6.00	2.00	20.00	9.60
M GROMMET-REAR WIPER	1.00	5.00	20.00	4.00
M ORNAMENT-KIA	1.00	76.00	20.00	60.80
M GARNISH-TAIL GATE,UPR	1.00	135.00	20.00	108.00
M COVER-RR BUMPER,UPR	1.00	576.00	20.00	460.80
M COVER-RR BUMPER LWR	1.00	211.00	20.00	168.80
M BRACKET-RR BUMPER SIDE LWR,RH	1.00	21.00	20.00	16.80
M LAMP ASSY-REAR FOG,RH	1.00	116.00	20.00	92.80
M BRACKET-FR BUMPER SIDE,RH	1.00	4.00	20.00	3.20
M WIRING HARNESS-R.P.A.S	1.00	251.00	20.00	200.80
M BRACKET-RR BUMPER RAIL,UPR	1.00	5.00	20.00	4.00
M BRACKET-RR BUMPER RAIL,LWR	1.00	5.00	20.00	4.00
M BRACKET-RR BUMPER LWR,CTR	1.00	5.00	20.00	4.00
M BRACKET-RR BUMPER RAIL,LWR	1.00	5.00	20.00	4.00
M BEAM-RR BUMPER	1.00	367.00	20.00	293.60
M ANTENNA ASSY-SMARTKEY	1.00	79.00	20.00	63.20
M STAY-RR BUMPER LH	1.00	159.00	20.00	127.20
M STAY-RR BUMPER RH	1.00	159.00	20.00	127.20
M BRACKET ASSY-RR BUMPER SIDE,LH	1.00	25.00	20.00	20.00
M BRACKET ASSY-RR BUMPER SIDE,RH	1.00	25.00	20.00	20.00
M HOLDER-BACK WARING SYSTEM OTR	2.00	4.00	20.00	6.40
M HOLDER-BACK WARING SYSTEM INR	2.00	4.00	20.00	6.40
M ULTRASONIC SENSOR ASSY-P.A.S	1.00	162.00	20.00	129.60
M ULTRASONIC SENSOR ASSY-P.A.S	1.00	162.00	20.00	129.60

Estimate

Confirm & accepted by

7% GST on	Nett 8655.60	8,655.60
		605.89
	Total Payable	9,261.49

 Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.