

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21012701/Vvy3e2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	23/12/2021	
	ATTN: KOH JANIC	E	Code	: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 8842Z	Veh. Inspected	GBK 7029R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S1M03OEW	Excess (\$)	0.00	
	Assign From	KOH JANICE	Assign Date	15/12/2021	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	JTFHT02P409990321	Colour	WHITE	
	Odometer	48730 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195 R15C	DURATURN	5 mm	
	L/H Front Tyre	195 R15C	DURATURN	5 mm	
	R/H Rear Tyre	195 R15C	DURATURN	5 mm	
	L/H Rear Tyre	195 R15C	DURATURN	5 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information					
	Accident Date	14/12/2021	Inspect Date / Time	17/12/2021 ( 11:00 AM )	
	Survey held at KIM SENG TECK MOTOR WORKS				
	BLK 3021A UBI ROAD 1 #01-42 SINGAPORE 408715				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

Report Ref No. CS3/ASM21012701/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser