

**COMFORTDELGRO
ENGINEERING**

VEHICLE I SHC2326L

NTUC

305497461

TYPE OF C: TP

SURVEY B': THEVAN /LKK

DATE : 12/12/21

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]

REPAIR ESTIMATE*

VEHICLE NO SHC2326L

DATE 09/12/2021 14.20

MAKE REG.03.09.2018

MODEL : HYUNDAI IONIQ G2

CHIANG /NTUC

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|--|-------------------------------|------|------------|--|
| 1 | FRONT BUMPER COVER | | DT / | \$430.90 |
| 1 | FRONT BUMPER BRACKET RH | | nc / | \$35.00 |
| 1 | HEADLAMP RH | | cray / | \$1,993.60 |
| 1 | HEADLAMP LAMP SUPPORT PANEL | | cray / | \$949.30 |
| 1 | FRONT BUMPER MOULDING CENTRE | | scr / | \$368.50 |
| 1 | DAY LIGHT RH | | scr / | \$642.50 |
| 1 | FRONT BUMPER GRILLE RH | | scr / | \$186.90 |
| 1 | FRONT FENDER RH | | DT / | \$588.80 |
| 1 | FRONT FENDER EMBLEM | | nc / | \$26.60 |
| 1 | FRONT FENDER UNDER SHIELD RH | | scr X ? | \$164.70 |
| 1 | RH WING MIRROR | | cut / | \$1,391.70 |
| 1 | FRONT WHEEL HUB COVER RH | | scr X | \$346.40 |
| | SUB TOTAL | | | \$7,124.90 |
| | 20.00% | | | \$1,424.98 |
| | DISCOUNTED TOTAL | | | \$5,699.92 |
| 1 | FRONT RH FENDER ADVERTISEMENT | | nc / | \$100.00 |
| | Labour Charge | | | \$100.00 |
| | Panel Beating | | / | \$700.00 |
| | Spray Paint | | 750 | \$800.00 |
| | Reset front wheel alignment | | NW X | \$60.00 |
| | Check lighting | | 20 | \$60.00 |
| | TOTAL LABOUR | | | \$1,620.00 |
| | ESTIMATE TOTAL | | | \$7,419.92 |
| Thuan @UKhauto.com 82235769 10/12/21 1615 L/S after repair photo 3days wp ✓ * Take support panel photo after disassemble | | | | LKK Auto Consultants hereby notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.