

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2326L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	DENTED	430.90	430.90
1	FRONT BUMPER BRACKET RH	NECESSARY	35.00	35.00
1	HEADLAMP RH	CRACKED	1,993.60	1,993.60
1	HEADLAMP LAMP SUPPORT PANEL	CRACKED	949.30	949.30
1	FRONT BUMPER MOULDING CENTRE	SCRATCHED	368.50	368.50
1	DAY LIGHT RH	SCRATCHED	642.50	642.50
1	FRONT BUMPER GRILLE RH	SCRATCHED	186.90	186.90
1	FRONT FENDER RH	DENTED	588.80	588.80
1	FRONT FENDER EMBLEM	NECESSARY	26.60	26.60
1	FRONT FENDER UNDER SHIELD RH	SERVICEABLE	164.70	-
1	RH WING MIRROR	CUT	1,391.70	1,391.70
1	FRONT WHEEL HUB COVER RH	SERVICEABLE	346.40	-
1	WIPER WASHER TANK	DENTED	210.00	210.00
	LESS 20% DISCOUNT		-1,466.98	-1,364.76
			5,867.92	5,459.04
	SPECIAL NETT ITEMS			
1	FRONT RH FENDER ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	LABOUR			
	PANEL BEATING.		700.00	700.00
	SPRAY PAINT.		800.00	750.00
	RESET FRONT WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	CHECK LIGHTING.		60.00	20.00
			1,620.00	1,470.00
	GRAND TOTAL		7,587.92	7,029.04





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		5,600.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21012703/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**