

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21012704/GQF3E2

Date: 05/04/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001683415		
Claimant Vehicle No :	SJQ2817P	Insured Vehicle No :	WC7262B		
Date of Loss:	14/12/2021	Nature of Claim:	TP	Claim No:	266990

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ2817P		
Make & Model:	HYUNDAI AVANTE, 1.6 HD DOHC ABS AIRBAG 2WD (A)	Engine No:	G4FC9U648528
Reg. Date:	30/04/2009 (Man. Year: 2009)	Chassis No:	KMH DU41BR9U752268
Colour:	White	Odometer:	0 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	45,114.72	16,154.00	28,960.72	64.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,800.00	4,350.00	4,450.00	50.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	53,914.72	20,504.00	33,410.72	61.97
Approved Total (Overridden) (S\$)		7,500.00		
Nett Amount (S\$)	53,914.72	7,500.00	46,414.72	86.09

INSPECTION

Date of Assignment:	16/12/2021	
Date Inspected:	16/12/2021 Inspected At:	PROVI AUTOWORKS PTE LTD (HQ) 8 Kaki Bukit Avenue 4, #02-24 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	12.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2022)

Parts: 143 HYUNDAI AVANTE 1.6 HD DOHC ABS AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJQ2817P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	2	*HEAD LAMP	Broken	1,160.00 FL	*680.00 FL
2	2	*HEAD LAMP BOTTOM BRACKET	Not Necessary	240.00 FL	*- FL
3	2	*HEAD LAMP TOP RUBBER	Not Necessary	178.00 FL	*- FL
4	1	*SUPPORT PANEL	Not Necessary	876.00 FL	*- FL
5	1	*AIR CON CONDENSOR	Not Necessary	913.70 FL	*- FL
6	1	*CONDENSER AIR CON PIPE	Not Necessary	321.00 FL	*- FL
7	1	*CONDENSER PRESSURE PIPE	Not Necessary	422.30 FL	*- FL
8	1	*CONDENSER SUCTION PIPE	Not Necessary	398.00 FL	*- FL
9	1	*RADIATOR ASSY	Not Necessary	870.60 FL	*- FL
10	1	*RADIATOR FAN COWLING	Not Necessary	273.00 FL	*- FL
11	1	*RADIATOR FAN MOTOR	Not Necessary	412.00 FL	*- FL
12	1	*RADIATOR FAN BLADE	Not Necessary	98.00 FL	*- FL
13	1	*FRONT BUMPER	Deformed	561.90 FL	*478.00 FL
14	1	*FRONT BUMPER SIDE RETAINER (2PCS)	Deformed (1Pc Only)	195.00 FL	*65.00 FL
15	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	433.20 FL	*- FL
16	1	*FRONT BUMPER SPONGE	Cracked	217.00 FL	*118.00 FL
17	1	*FRONT BUMPER LOWER GRILLE	Missing	255.80 FL	*255.80 FL
18	2	*FRONT BUMPER FOG COVER	Deformed	202.40 FL	*202.40 FL
19	1	*FRONT BUMPER LOWER COVER	Torn	288.10 FL	*47.50 FL
20	1	*WIPER TANK	Broken	188.20 FL	*154.70 FL
21	1	*WIPER TANK MOTOR	Cut	266.60 FL	*114.60 FL
22	1	*FRONT FENDER (2PCS)	Buckled (1Pc Only)	1,242.40 FL	*466.50 FL
23	1	*FRONT FENDER COWLING (2PCS)	Deformed (1Pc Only)	379.40 FL	*189.70 FL
24	2	*FRONT FENDER INNER BRACKET	Not Necessary	156.00 FL	*- FL
25	1	*FRONT WHEEL HOUSING RH	Repair	566.80 FL	*- FL
26	1	*FRONT ABSORBER	O/S Bent / N/S Not Necessary	669.20 FL	*334.60 FL
27	1	*FRONT ABSORBER TOP MOUNTING	O/S Bent / N/S Not Necessary	332.00 FL	*166.00 FL
28	1	*FRONT LOWER ARM	O/S Bent / N/S Not Necessary	821.20 FL	*410.60 FL
29	1	*FRONT KNUCKLE ARM	O/S Bent / N/S Not Necessary	807.80 FL	*403.90 FL
30	1	*FRONT WHEEL BEARING	O/S Bent / N/S Not Necessary	471.80 FL	*198.00 FL
31	1	*FRONT ANTI ROLL BAR	Bent	344.70 FL	*344.70 FL
32	2	*FRONT ANTI ROLL BAR LINK	Bent	240.00 FL	*240.00 FL
33	1	*STEERING RACK AND PINION	Bent	1,877.20 FL	*1,573.00 FL
34	2	*FRONT DRIVE SHAFT	Not Necessary	2,944.60 FL	*- FL
35	1	*FRONT CROSSMEMBER	Bent	987.20 FL	*987.20 FL
36	1	*FRONT DOOR INNER PILLAR RH	Repair	768.30 FL	*- FL
37	1	*FRONT DOOR OUTER PILLAR RH	Repair	788.20 FL	*- FL
38	1	*FRONT DOOR RH	Buckled	1,440.00 FL	*1,091.00 FL
39	2	*FRONT DOOR BLACK STICKER RH	Necessary	112.00 FL	*26.00 FL
40	1	*FRONT DOOR OUTER MOULDING RH	Not Necessary	178.40 FL	*- FL
41	2	*FRONT DOOR HINGE RH	Bent	178.00 FL	*178.00 FL
42	1	*FRONT DOOR CHECKER RH	Bent	112.40 FL	*112.40 FL
43	1	*FRONT DOOR SIDE MIRROR RH	Distorted	754.90 FL	*652.00 FL
44	1	*FRONT DOOR OUTER HANDLE RH	Cut	247.90 FL	*188.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*FRONT DOOR OUTER HANDLE SIDE COVER RH	Cut	45.00 FL	*45.00 FL
46	1	*FRONT DOOR INNER LOCK RH	Jammed	455.00 FL	*291.00 FL
47	1	*FRON DOOR LOCK CATCH RH	Not Necessary	46.00 FL	*- FL
48	1	*FRONT DOOR WEATHERSTRIP RH	Not Necessary	189.00 FL	*- FL
49	1	*FRONT DOOR INNER TRIM RH	Not Necessary	672.30 FL	*- FL
50	1	*FRONT DOOR REGULATOR MOTOR RH	Not Necessary	457.00 FL	*- FL
51	1	*FRONT DOOR REGULATOR GEAR RH	Not Necessary	312.00 FL	*- FL
52	1	*FRONT DOOR CHANNEL RH	Not Necessary	87.90 FL	*- FL
53	1	*FRONT DOOR CHANNEL SEAL RH	Necessary	159.10 FL	*124.00 FL
54	1	*FRONT DOOR FRAME WEATHERSTRIP RH	Not Necessary	255.20 FL	*- FL
55	1	*FRONT DOOR BOTTOM STEP TRIM RH	Not Necessary	176.00 FL	*- FL
56	1	*CENTER INNER PILLAR RH	Repair	654.70 FL	*- FL
57	1	*CENTER OUTER PILLAR RH	Repair	662.10 FL	*- FL
58	1	*ROCKER PANEL RH	Repair	1,799.60 FL	*- FL
59	1	*REAR DOOR RH	Buckled	1,398.40 FL	*1,099.00 FL
60	2	*REAR DOOR BLACK STICKER RH	Necessary	90.00 FL	*26.00 FL
61	1	*REAR DOOR OUTER MOULDING RH	Not Necessary	180.80 FL	*- FL
62	1	*REAR DOOR OUTER HANDLE RH	Distorted	247.90 FL	*192.00 FL
63	1	*REAR DOOR OUTER HANDLE SIDE COVER RH	Missing	45.00 FL	*45.00 FL
64	2	*REAR DOOR HINGE RH	Bent	178.00 FL	*178.00 FL
65	1	*REAR DOOR CHECKER RH	Bent	112.40 FL	*112.40 FL
66	1	*REAR DOOR INNER LOCK RH	Jammed	394.70 FL	*291.00 FL
67	1	*REAR DOOR LOCK CATCH RH	Not Necessary	46.00 FL	*- FL
68	1	*REAR DOOR WEATHERSTRIP RH	Not Necessary	189.00 FL	*- FL
69	1	*REAR DOOR INNER TRIM RH	Not Necessary	622.00 FL	*- FL
70	1	*REAR DOOR REGULATOR MOTOR RH	Not Necessary	466.10 FL	*- FL
71	1	*REAR DOOR REGULATOR GEAR RH	Not Necessary	312.00 FL	*- FL
72	1	*REAR DOOR CHANNEL RH	Not Necessary	98.00 FL	*- FL
73	1	*REAR DOOR CHANNEL SEAL RH	Necessary	155.00 FL	*124.00 FL
74	1	*REAR DOOR FRAME WEATHERSTRIP RH	Not Necessary	247.00 FL	*- FL
75	1	*REAR DOOR BOTTOM STEP TRIM RH	Not Necessary	188.10 FL	*- FL
76	1	*REAR WINDSCREEN MOULDING	Necessary	198.00 FL	*198.00 FL
77	1	*REAR FENDER GLASS WITH MOULDING RH	Necessary	465.00 FL	*288.00 FL
78	1	*REAR FENDER RH	Buckled	875.40 FL	*875.40 FL
79	1	*REAR FENDER COWLING RH	Not Necessary	152.00 FL	*- FL
80	1	*REAR FENDER INNER HOUSING RH	Not Necessary	577.40 FL	*- FL
81	1	*REAR ABSORBER RH	Not Necessary	367.00 FL	*- FL
82	1	*REAR UPPER ARM RH	Not Necessary	276.40 FL	*- FL
83	1	*REAR LOWER ARM RH	Not Necessary	427.80 FL	*- FL
84	1	*REAR KNUCKLE ARM RH	Not Necessary	564.00 FL	*- FL
85	1	*REAR WHEEL BEARING RH	Jammed	231.30 FL	*231.30 FL
86	1	*TAILLAMP RH	Not Necessary	354.00 FL	*- FL
87	1	*REAR BUMPER	Cut	698.00 FL	*495.00 FL
88	1	*REAR BUMPER SIDE RETAINER (2PCS)	Deformed (1Pc Only)	99.60 FL	*49.80 FL
89	1	*SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
90	1	*RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS
91	1	*FRONT FENDER INNER SHIELD CLIP	Necessary	40.00 FS	*30.00 FS
92	1	*FRONT WHEEL HOUSING SEALANT	Not Necessary	80.00 FS	*- FS
93	1	*FRONT BUMPER CLIP	Necessary	50.00 FS	*40.00 FS
94	1	*FRONT BUMPER LOWER COVER CLIP	Not Necessary	40.00 FS	*- FS
95	1	*FRONT BUMPER DIFFUSER	Cracked	1,500.00 FS	*1,200.00 FS
96	3	*TYRE	Cut	1,500.00 FS	*300.00 FS
97	3	*SPORT RIM	Cut	4,200.00 FS	*1,050.00 FS
98	1	*FRONT DOOR INNER PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
99	1	*FRONT DOOR OUTER PILLAR SEALANT	Necessary	80.00 FS	*40.00 FS
100	1	*FRONT DOOR SEALANT	Not Necessary	80.00 FS	*- FS
101	1	*FRONT DOOR INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
102	1	*FRONT DOOR BOTTOM STEP TRIM CLIP	Not Necessary	30.00 FS	*- FS
103	1	*CENTER INNER PILLAR SEALANT	Not Necessary	80.00 FS	*- FS

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
104	1	*CENTER OUTER PILLAR SEALANT	Necessary	80.00 FS	*40.00 FS
105	1	*ROCKER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
106	1	*SIDE SKIRT (2PCS)	Cut (1Pc Only)	1,800.00 FS	*600.00 FS
107	1	*REAR DOOR SEALANT	Not Necessary	80.00 FS	*- FS
108	1	*REAR DOOR INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
109	1	*REAR DOOR BOTTOM STEP TRIM CLIP	Not Necessary	30.00 FS	*- FS
110	1	*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*20.00 FS
111	1	*REAR FENDER GLASS SEALANT	Necessary	80.00 FS	*20.00 FS
112	1	*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
113	1	*REAR FENDER COWLING CLIP	Necessary	40.00 FS	*20.00 FS
114	1	*REAR FENDER INNER HOUSING SEALANT	Not Necessary	80.00 FS	*- FS
115	1	*REAR BUMPER CLIP	Necessary	50.00 FS	*40.00 FS
116	1	*REAR BUMPER DIFFUSER	Cracked	1,400.00 FS	*1,200.00 FS
117	1	*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	53,398.40	19,022.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	8,283.68	2,868.50
Total Parts (\$\$)	45,114.72	16,154.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	3,200.00	1,800.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,800.00	1,800.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	100.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	200.00	80.00
5	REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST	New	200.00	0.00
6	DISMANTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST	New	250.00	0.00
7	REMOVE AND INSTALL FRONT DOOR PART	New	200.00	60.00
8	REMOVE AND INSTALL REAR DOOR PART	New	200.00	60.00
9	REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	600.00	200.00
10	REMOVE AND INSTALL REAR UNDER CARRIAGE	New	600.00	100.00
11	TO CHECK FOUR WHEEL ALIGNMENT	New	100.00	60.00
12	REMOVE AND INSTALL REAR FENDER GLASS	New	150.00	40.00
13	REMOVE AND INSTALL REAR WINDSCREEN	New	200.00	120.00
Gross Labour Cost (\$\$)			8,800.00	4,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >