Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte.

Ltd.

4 Shenton Way #21-01 SGX Centre 2

Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Nor Azian Binte Noordin Date: 29 Dec 2021

Preliminary Advice

Insured : WC7262B

Vehicle No

TP Vehicle Accident Date : SJQ2817P : 14/12/2021

No

Assignment Date: 16/12/2021 Make : HYUNDAI AVANTE

Date of : 16/12/2021 Est. Duration of

: 12 Inspection Repair

Inspection At: PROVI AUTOWORKS PTE LTD (HQ)

8 KAKI BUKIT AVENUE 4, #02-24 PREMIER @ KAKI BUKIT

SINGAPORE 415875

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 53,914.72 **Revised Amount** :S\$ 25,093.92 Check Items (Estimated) :S\$ 16,170.24 Total :S\$ 41,264.16

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 15,000.00 COE / PARF Rebate :S\$ 6,194.00

Salvage value .S.	Salvage	Value	:S\$
-------------------	---------	-------	------

Margin for Repair :S\$ 8,806.00

Remarks

()	The vehicle is economical for repair
()	The vehicle is not economical for repair
()	Part-by-Part repair
()	Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.