

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012705/EVY3N2**Date:** 17/01/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00147682100

**Claimant Vehicle No :** SLK7401E **Insured Vehicle No :** XE4522Z

Date of Loss: 14/12/2021 Nature of Claim: TP Claim No: SNM21D207298/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK7401E**

Make & Model: TOYOTA LEXUS, 2.5 ES250 AUTO (A) Engine No: 2ARF260095

Reg. Date: 25/01/2017 (Man. Year: 2016) Chassis No: JTHBJ1GG802095621

Colour: Silver Odometer: 66070 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55R17 Rear Tyre Size: 215/55R17

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,926.00	3,615.30	3,310.70	47.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,931.50	9,037.50	2,894.00	24.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,857.50</b>	<b>12,652.80</b>	<b>6,204.70</b>	<b>32.90</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,320.03</b>	<b>885.70</b>	<b>434.33</b>	<b>32.90</b>
<b>Nett Amount (S\$)</b>	<b>20,177.53</b>	<b>13,538.50</b>	<b>6,639.03</b>	<b>32.90</b>

INSPECTION

Date of Assignment: 15/12/2021

Date Inspected: 21/12/2021 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)  
2 Pandan Crescent  
Singapore 128462

Estimated Period of Repair: 8.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2022)
<b>Parts:</b> 143	TOYOTA LEXUS 2.5 ES250 AUTO (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLK7401E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY RR	Dented	1,212.90 FS	*1,212.90 FS
2	1		*WEATHERSTRIP,RR	Necessary	60.70 FS	*60.70 FS
3	1		*STRIPE RR DOOR	Necessary	38.60 FS	*38.60 FS
4	1		*STRIPE RR DOOR	Necessary	70.00 FS	*70.00 FS
5	1		*PROTECTOR,RR DOOR	Necessary	11.30 FS	*11.30 FS
6	1		*WEATHERSTRIP,RR	Not Necessary	285.60 FS	*- FS
7	17		*RETAINER,DOOR	Necessary	91.80 FS	*91.80 FS
8	1		*WEATHERSTRIP,RR	Necessary	62.40 FS	*62.40 FS
9	1		*WEATHERSTRIP,RR	Necessary	62.40 FS	*62.40 FS
10	1		*HANDLE ASSY,DOOR	Repair	492.90 FS	*- FS
11	1		*COVER,RR DOOR	Not Necessary	49.50 FS	*- FS
12	1		*PAD,FR DOOR OUTSIDE	Not Necessary	21.00 FS	*- FS
13	1		*PAD,FR DOOR OUTSIDE	Not Necessary	20.70 FS	*- FS
14	1		*PROTECTOR,QUART	Necessary	28.80 FS	*28.80 FS
15	1		*PANEL,QUARTER RH	Dented	1,532.20 FS	*1,532.20 FS
16	1		*PANEL SUB-ASSY RR	Not Necessary	214.00 FS	*- FS
17	1		*GLASS,BACK WINDOW	Not Necessary	1,671.10 FS	*- FS
18	1		*DAM,WINDOW GLASS	Not Necessary	29.20 FS	*- FS
19	1		*MOULDING,BACK WINDOW	Not Necessary	60.70 FS	*- FS
20	1		*MOULDING RR DOOR	Necessary	98.50 FS	*98.50 FS
21	19		*RIVET	Necessary	28.50 FS	*28.50 FS
22	2		*SIKA 182010 SIKA TACK GO! (BLA)	Not Necessary	216.00 FS	*- FS
23	1		*SIKA 207,G+P ADHESIVE PRIMER	Not Necessary	200.00 FS	*- FS
24	1		*PANEL BONDING AD	Necessary	267.20 FS	*267.20 FS
25	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>6,926.00</b>	<b>3,615.30</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON RHS REAR DOOR,RHS REAR FENDER AND FIX NEW PARTS	New	5,196.00	4,330.00
2	TO SPRAY PAINT ON RHS REAR DOOR,RHS REAR FENDER AND REAR PANEL	New	2,968.00	2,226.00
3	TO REMOVE AND TRANSFER RHS REAR DOORS COMPONENT AND MECHANISM TO NEW DOOR	New	866.00	866.00
4	SUPPLY RHS REAR DOOR SEALANT	New	100.00	100.00
5	TO REMOVE AND RE-INSTALL REAR SEAT,SIDE TRIM,GARNISH ETC TO ENABLE REPAIR	New	866.00	866.00
6	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS	New	866.00	0.00
7	REPLACE REAR WINDSCREEN SOLAR FILM	New	420.00	0.00
8	TO REMOVE AND RE-INSTALL REAR SENSOR TO ENABLE REPAIR	New	216.50	216.50
9	TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST	New	216.50	216.50
10	TO RESET ECU & REPROGRAMME	New	216.50	216.50
<b>Gross Labour Cost (\$\$)</b>			<b>11,931.50</b>	<b>9,037.50</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**