

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21012706/KVF3E2

**Date:** 23/05/2022

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/21-426736-CA
<b>Claimant Vehicle No :</b>	SMQ7558T	<b>Insured Vehicle No :</b>	FBL1819L
Date of Loss:	10/12/2021	Nature of Claim:	TP
		Claim No:	MSC/V/21-000522

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ7558T	Engine No:	1NZR783014
Make & Model:	TOYOTA SIENTA HYBRID, 1.5 X CVT (A)	Chassis No:	NHP1707172757
Reg. Date:	29/11/2019 (Man. Year: 2019)	Odometer:	31941 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Toyo 8 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Toyo 8 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,761.07	1,761.07	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	1,200.00	200.00	14.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,161.07</b>	<b>2,961.07</b>	<b>200.00</b>	<b>6.33</b>
<b>+ GST 7.00/7.00% (S\$)</b>	221.27	207.27	14.00	6.33
<b>Nett Amount (S\$)</b>	<b>3,382.34</b>	<b>3,168.34</b>	<b>214.00</b>	<b>6.33</b>

### INSPECTION

Date of Assignment:	15/12/2021	
Date Inspected:	21/01/2022 Inspected At:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT Singapore 568047
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2022)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMQ7558T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	309.10 FL	*309.10 FL
2	1		*REAR BUMPER TOP PROTECTOR	Dented	189.50 FL	*189.50 FL
3	1		*REAR BUMPER TRIANGLE GARNISH	Dented	45.20 FL	*45.20 FL
4	1		*REAR BUMPER LH SIDE PAD	Dented	129.10 FL	*129.10 FL
5	6		*REAR BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
6	1		*REAR TAILGATE	Bent	1,110.90 FL	*1,110.90 FL
7	1		*TAILGATE LOGO	Necessary	67.50 FL	*67.50 FL
8	1		*TAILGATE EMBLEM HYBRID	Necessary	56.00 FL	*56.00 FL
9	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	99.80 FL	*99.80 FL
10	1		*SET REVERSE SENSOR	Scratched	200.00 FS	*200.00 FS
11	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,268.10</b>	<b>2,268.10</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	507.03	507.03
<b>Total Parts (\$\$)</b>	<b>1,761.07</b>	<b>1,761.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIT REAR BUMPER & ATTACHMENTS, TAILGATE & ATTACHMENTS KNOCKING & REPAIR REAR END PANEL & REALIGN THE SAME	New	500.00	400.00
3	PUTTY & RESPRAY REAR BUMPER , TAILGATE , REAR END PANEL & ALL AFFECTED AREAS	New	700.00	600.00
4	REMOVE & REFIX REVERSE CAMERA RESET & REALIGN THE SAME	New	50.00	50.00
5	RUSTPROOFING	New	30.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>1,400.00</b>	<b>1,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >