

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21012707/ETF3N2**Date:** 23/03/2022**REFERENCE**

Insured/Claimant:	STEPHANIE QUEK ZHENG LING	Policy No:	7210016910	
Date of Loss:	14/12/2021	Nature of Claim:	OD	Claim No: 5167843302SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EX4D		
Make & Model:	CITROEN GRAND C4 PICASSO, 1.6 BLUEHDI EAT6 (A)	Engine No:	10FJCC2285229
Reg. Date:	03/03/2017 (Man. Year: 2016)	Chassis No:	VF73A5GZTGJ811729
Colour:	Grey	Odometer:	36777 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$65,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R17	Rear Tyre Size:	205/55R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,350.60	4,089.80	260.80	5.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,465.00	2,205.00	1,260.00	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,815.60	6,294.80	1,520.80	19.46
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	7,515.60	5,994.80	1,520.80	20.24
+ GST 7.00/7.00% (\$\$)	526.09	419.64	106.45	20.23
Nett Amount (\$\$)	8,041.69	6,414.44	1,627.25	20.24

INSPECTION

Date of Assignment: 15/12/2021

Date Inspected: 16/12/2021 Inspected At:

Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,031.00 FL	*1,031.00 FL
2	1		*BUMPER MOULDING	Cut	207.00 FL	*207.00 FL
3	1		*BUMPER MOULDING	Not Necessary	207.00 FL	*- FL
4	1		*BUMPER MOULDING	Cut	227.00 FL	*227.00 FL
5	1		*BRACKET SET	Necessary	125.00 FL	*125.00 FL
6	1		*BUMPER BRACKET	Necessary	224.00 FL	*224.00 FL
7	1		*FRONT WING RH ASS	Dented	571.00 FL	*571.00 FL
8	1		*HEADLIGHT ASSY RH	Broken	1,667.00 FL	*1,667.00 FL
9	1		*DISTRIB CHAMBER	Dented	840.00 FL	*840.00 FL
10	1		*DIST CHB BRACKET	Broken	43.00 FL	*43.00 FL
11	1		*DIST CHB BRACKET	Bent	43.00 FL	*43.00 FL
12	1		*FOG HEADLIGHT	Broken	128.00 FL	*128.00 FL
13	1		*REAR DUCT RH	Not Necessary	119.00 FL	*- FL
14	1		*SUNDRIES	Necessary	5.00 FS	*5.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,437.00	5,111.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,086.40	1,021.20
Total Parts (S\$)	4,350.60	4,089.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,FRT RH FENDER & AFFECTED AREA	New	1,500.00	750.00
2	PAINT WORK ON FRT BUMPER,FRT RH FENDER & FRT RH DOOR	New	1,140.00	1,140.00
3	REPLACE TURBO INTERCOOLER ASSY	New	500.00	0.00
4	PERFORM RUST PREVENTION	New	50.00	40.00
5	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	50.00	50.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	225.00	225.00
Gross Labour Cost (\$)			3,465.00	2,205.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >