



ALG - OD CLAIM
SURVEY: 16/12/21
LKK - STEVE

VEHICLE NO : EX 4 D

MODEL : CIT/GC4P 1.6 THP 165

WIP : 17250

Material	:	\$	<u>4,084.80</u>
Labour	:	\$	<u>2,210.00</u>
Sub-Total	:	\$	<u>6,294.80</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>5,994.80</u>
GST 7%	:	\$	<u>419.64</u>
Grand Total	:	\$	<u>6,414.44</u>
Finalise By/Date : <u>Amey on 23/02/22</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (weekend)

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name /Ms Stephanie Quek Zhen Ling Reg No/Reg Date EX4D*CC17S5 / 03/03/2017 Date In/Mileage 14/02/2022/ 38848 Chassis/Package VF73A5GZTGJ811729 /NOTES Engine No 10FJCC2285229 Make/Model CIT/GC4P 1.6 THP 165 EAT6 INTENSIVE_ML Colour/Trim F4M GRIS ARTENSE / IXF YATAGO GREY



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	23/02/2022/ 13:29	BLK	884 / Lauro Songcuan	17250	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER, FRONT RH FENDER & AFFECTED AREAS				750.00 ✓
E PNT98000 SPRAY PAINT ON FRONT BUMPER, FRONT RH FENDER & FRONT RH DOOR				1140.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED PORTIONS				40.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				50.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				225.00 ✓
M SUNDRY SUNDRIES				5.00 ✓
X EXC INSURANCE EXCESS				-300.00
X FRONT BUMPER ✓	1.00	1031.00	20.00	824.80 ✓
X BUMPER MOULDING ✓	1.00	207.00	20.00	165.60 ✓
X BUMPER MOULDING ✓	1.00	227.00	20.00	181.60 ✓
X BRACKET SET ?	1.00	125.00	20.00	100.00 ?
X BUMPER BRACKET ?	1.00	224.00	20.00	179.20 ?
X FRONT WING RH ASS ✓	1.00	571.00	20.00	456.80 ✓
X HEADLIGHT ASSY RH ✓	1.00	1667.00	20.00	1333.60 ✓
X DISTRIB CHAMBER ✓	1.00	840.00	20.00	672.00 ✓
X DIST CHB BRACKT ✓	1.00	43.00	20.00	34.40 ✓
X DIST CHB BRACKT ✓	1.00	43.00	20.00	34.40 ✓
X FOG HEADLIGHT ✓	1.00	128.00	20.00	102.40 ✓
Z TEXT AIG - OD CLAIM DOA: 14/12/2021 SURVEY: STEVE (LKK) 16/12/2021 05 DAYS				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	4,084.80		Nett	5,994.80
Labour	2,165.00	7% GST on	5994.80	419.64
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00		Total Payable	6,414.44
Sundry/Others	-255.00		Paid	0.00
Total(w/o GST)	5,994.80		Total Due	6,414.44

Payment should be made strictly by NETS, credit cards or PayNow (via QR code or UEN) only. Thank you.
 Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

CAR NO: EX4DWIP: 17250

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Bracket Set	? / SUPP			C1610194380
2	Bumper Bracket	? / SUPP			C16175370XY
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: C4SURVEYOR: Steve. Lkh

EX 4D

Before -

User:
Vehicle : C4 PICASSO / C4 SPACETOURER
VIN: VF73A5GZTGJ811729

Print date : Saturday, 19 February 2022 10:36:44

Start of vehicle session :

Tool version : 09.111



Your tool is not up to date. Please download versions 9.122

Home

Documentation

Measurements

Reports

PROGRESS OF THE AUTOMATIC DETECTION OF THE VEHICLE

- ✓ VIN : VF73A5GZTGJ811729
- ✓ Vehicle data retrieved
- ✓ Identification of the vehicle complete

CITROEN C4 PICASSO / C4 SPACETOURER (B78) B
(EP6FDT) BVA 6 RAPPORTS 1



Automatic detection of the veh



Global test

Expert/Global test

Vehicle\menu_tgref.s : 81_02

FAMILY NO.

CONTROL UNIT

11



Built-in systems interface

BSI2010_EV (11 Faults)

U1F32 87

Fault: absence of communication with the driver's door control pad

Properties

Cause

Local

Status

Intermittent

Features

-

B181A 87

Fault in the response from the electric steering lock to the request for locking/unlocking

Properties

Cause

Local

Status

Intermittent

Features

No reply

B1808 87

Fault in the unlocking of the immobiliser by the engine management ECU

User: DF15000

Vehicle : C4 PICASSO C4 SPACETOURER/C4

SPACETOURER (B78)

VIN: VF73A5GZTGJ811729

Ex 4-D

After

Print date : Saturday, 19 February 2022 10:49:47

Start of vehicle session : 19/02/2022 - 10:36

Tool version : 09.111



Global test

Expert/Global test

Vehicle\menu_tgref.s : 81_02

FAMILY NO.

CONTROL UNIT

1



Built-in systems interface

BSI2010_EV (1 Faults)

B1003 00

Configuration fault (warning, this fault may be a phantom fault)

Properties

Cause

Local

Status

Intermittent

Features

-

1



Engine management ECU

MED17_4_4 (1 Faults)

P160A 54

Downloading / Configuration

Properties

Status

Intermittent

Characterisation of the fault

Approval number not entered

List of associated variables

Status of the internal
combustion engine

Cut off stalled

Ancillaries battery charge
status

61

%

Battery temperature

40.0

°C

Power relay control status

Power relay controlled



Right-hand windscreen wiper motor

MOTED_UDS



Air conditioning

BCC



Instrument panel

★ *ECU not recognised*

Down-grade mode: this information is not guaranteed



Rain and brightness sensor

PLUIE_LUMINOSITE_UDS




Airbags and pretensioners ECU

RBG_UDS




Battery charge status control unit

BECB_GEN2



Multifunction control panel

FMUX



Parking assistance

AAS_UDS



Telematic unit (RTx) or audio-navigation

★ *ECU not recognised*


Down-grade mode: this information is not guaranteed



Dynamic headlamp height adjuster

★ *ECU not recognised*

Down-grade mode: this information is not guaranteed



Electronic key reader

Communication error




Signalling fuse box

BSG_S




Driver's door module

PDPC_UDS



Automatic gearbox electric control ECU

COMELEC2




Seat driver position memory module.

Not present




Right-hand reversible seat belt inertia reel

Not present




Left-hand reversible seat belt inertia reel

Not present



Supplies protection and management unit

Not present




Hands-free unit

Not present




Service module / Independent telematic unit

Not present




Diesel additive pump

Not present



Panoramic visual assistance ECU

Not present



Driver's seat comfort ECU

Not present

Help