

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012708/GNY3M4**Date:** 21/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00120292100

**Claimant Vehicle No :** SNC4703Y **Insured Vehicle No :** SKX4439K

Date of Loss: 13/12/2021 Nature of Claim: TP Claim No: SNM21D207295/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNC4703Y**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB7604109

Reg. Date: 22/10/2021 (Man. Year: 2021) Chassis No: GP72203332

Colour: White Odometer: 8151 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm

Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,501.76	1,277.60	224.16	14.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	700.00	210.00	23.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,411.76</b>	<b>1,977.60</b>	<b>434.16</b>	<b>18.00</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	168.82	138.43	30.39	18.00
<b>Nett Amount (\$\$)</b>	<b>2,580.58</b>	<b>2,116.03</b>	<b>464.55</b>	<b>18.00</b>

**INSPECTION**

Date of Assignment: 15/12/2021

Date Inspected: 29/12/2021 Inspected At: 160 SIN MING DRIVE #03-03  
SIN MING AUTO CITY  
SINGAPORE 575722  
REPAIRER: VIN'S MOTOR PTE LTD

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Jul 2022)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC4703Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Buckled	1,293.50 FL	*1,293.50 FL
2	1		*REAR TAILGATE GLASS MOULDING	Necessary	153.20 FL	*118.20 FL
3	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	55.20 FL	*55.20 FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	80.10 FL	*80.10 FL
5	1		*REAR BUMPER CHROME MOULDING	Not Necessary	220.20 FL	*- FL
6	1		*REAR WINDSCREEN GUM	Necessary	60.00 FS	*40.00 FS
					<b>Sub Total (\$)</b>	<b>1,862.20</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	<b>360.44</b>
					<b>Total Parts (\$)</b>	<b>1,501.76</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
2	TO REPAIR DAMAGES	New	380.00	200.00
3	TO SPRAY PAINTING	New	380.00	380.00
<b>Gross Labour Cost (S\$)</b>			<b>910.00</b>	<b>700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >