

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/TMI21012709/KVCN2**Date:** 07/01/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR006485
<b>Claimant Vehicle No :</b>	SHD9970A	<b>Insured Vehicle No :</b>	SFR3113Y
Date of Loss:	10/12/2021	Nature of Claim:	TP
		Claim No:	M2105802

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD9970A</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2G81551
Reg. Date:	24/09/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU003091526
Colour:	Metallic Pearl White/Red	Odometer:	183965 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,272.77	5,042.35	7,230.42	58.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,290.00	2,030.00	8,260.00	80.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>22,562.77</b>	<b>7,072.35</b>	<b>15,490.42</b>	<b>68.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,579.39</b>	<b>495.06</b>	<b>1,084.33</b>	<b>68.65</b>
<b>Nett Amount (S\$)</b>	<b>24,142.16</b>	<b>7,567.41</b>	<b>16,574.75</b>	<b>68.65</b>

INSPECTION

Date of Assignment:	16/12/2021	
Date Inspected:	14/12/2021	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	6.0 days	

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 07 Jan 2022)

**Parts:** 144      TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHD9970A)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOX,DECK FLOOR,RH	Serviceable	313.60 FL	-	*- FL
2	1		*BOX,DECK FLOOR,LH	Serviceable	313.00 FL	-	*- FL
3	1		*COVER,FLOOR UNDER NO 1 LH	Serviceable	175.10 FL	-	*- FL
4	1		*COVER,FLOOR UNDER NO 2 RH	Serviceable	241.90 FL	-	*- FL
5	1		*COVER,REAR FLOOR CTR	Serviceable	229.90 FL	-	*- FL
6	1		*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	-	*- FL
7	1		*PANEL SUB-ASSY,BODY LOWER BACK	Bent	651.00 FL	-	*651.00 FL
8	1		*STAY ASSY,BACK DOOR,LH	Serviceable	242.50 FL	-	*- FL
9	1		*STAY ASSY,BACK DOOR,RH	Serviceable	242.50 FL	-	*- FL
10	1		*HINGE ASSY,BACK DOOR,LH	Repair	61.00 FL	-	*- FL
11	1		*HINGE ASSY,BACK DOOR,RH	Repair	61.00 FL	-	*- FL
12	1		*PANEL SUB-ASSY,QUARTER,RH	Repair	871.50 FL	-	*- FL
13	1		*LINER REAR WHEEL HOUSE,RH	Serviceable	139.80 FL	-	*- FL
14	1		*SET PARKING AID	Dented	700.00 FS	-	*220.00 FS
15	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	-	*50.00 FS
16	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	-	*80.00 FS
17	1		*WINDSCREEN MOULDING	Necessary	200.00 FS	-	*200.00 FS
18	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	-	*30.00 FS
19	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	-	*- FS
20	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	-	*- FS
21	1		*REAR SPOILER CLIP	Not Necessary	70.00 FS	-	*- FS
22	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	-	*- FS
23	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	-	*30.00 FS
24	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	-	*30.00 FS
25	1		*SET BUMPER CLIP FRT	Not Necessary	95.00 FS	-	*- FS
26	1		*REAR NUMBER PLATE WITH MOULDING	Dented	200.00 FS	-	*45.00 FS
27	1		*COVER REAR BUMPER	Bent	485.60 FL	-	*485.60 FL
28	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Bent	332.70 FL	-	*332.70 FL
29	1		*COVER,REAR BUMPER LOWER	Dented	22.00 FL	-	*22.00 FL
30	1		*GUARD,REAR BUMPER CENTER	Bent	374.50 FL	-	*374.50 FL
31	1		*RETAINER,REAR BUMPER SIDE,LH	No such part	132.60 FL	-	*- FL
32	1		*RETAINER,REAR BUMPER SIDE,RH	No such part	132.60 FL	-	*- FL
33	1		*REFLECTOR ASSY,REFLEX,LH	Serviceable	39.00 FL	-	*- FL
34	1		*REFLECTOR ASSY,REFLEX,RH	Cracked	39.00 FL	-	*39.00 FL
35	1		*LENS & BODY,REAR COMBINATION LAMP,RH	Broken	339.60 FL	-	*339.60 FL
36	1		*LENS & BODY,REAR COMBINATION LAMP NO 2 RH	Cracked	261.00 FL	-	*261.00 FL
37	1		*PANEL SUB-ASSY,BACK DOOR	Bent	1,147.80 FL	-	*1,147.80 FL
38	1		*GLASS,BACK WINDOW FIX	Shattered	761.40 FL	-	*761.40 FL
39	1		*MOULDING,BACK WINDOW,OUTSIDE LH NO 2	Necessary	30.90 FL	-	*30.90 FL
40	1		*SPOILER SUB-ASSY,REAR	Serviceable	1,575.40 FL	-	*- FL
41	1		*LAMP ASSY,CENTER STOP	Serviceable	192.30 FL	-	*- FL
42	1		*LAMP ASSY,REAR RH	Cracked	293.60 FL	-	*293.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
43	1		*PLATE,LUGGAGE COMPARTMENT DOOR NAME,NO 2	Necessary	54.60 FL	-	*54.60 FL
44	1		*PLATE BACK DOOR NAME NO 1	Necessary	54.60 FL	-	*54.60 FL
45	1		*ORNAMENT SUB-ASSY,BACK DOOR	Necessary	47.90 FL	-	*47.90 FL
46	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Cracked	913.60 FL	-	*913.60 FL
47	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	259.20 FL	-	*- FL
48	1		*WEATHERSTRIP,BACK DOOR	Serviceable	372.30 FL	-	*- FL
49	1		*ANTENNA ELECTRICAL KEY	Serviceable	72.00 FL	-	*- FL
50	1		*PAN,REAR FLOOR	Repair	583.40 FL	-	*- FL
51	1		*BOARD,REAR FLOOR NO 1	Serviceable	519.00 FL	-	*- FL
52	1		*PANEL ASSY,DECK TRIM SIDE,LH	Serviceable	355.90 FL	-	*- FL
53	1		*PANEL ASSY,DECK TRIM SIDE,RH	Serviceable	355.90 FL	-	*- FL
54	1		*BOX,DECK FLOOR REAR	Serviceable	105.80 FL	-	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 15,653.70 6,494.80**  
**- List Item Discount on L Items 25.00/25.00% (\$\$) 3,380.93 1,452.45**

**Total Parts (\$\$) 12,272.77 5,042.35**

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	180.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	80.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	700.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	60.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT,VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	60.00
11	TOWING FEES	New	150.00	0.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	880.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
15	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	220.00	0.00
17	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
18	TO LIFT-UP/OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
19	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS-MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	0.00
20	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
21	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>10,290.00</b>	<b>2,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >