

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012711/GNY3Q2**Date:** 30/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00153512101

Claimant Vehicle No : SMN8742L **Insured Vehicle No :** YN9698H

Date of Loss: 13/12/2021 Nature of Claim: TP Claim No: SNM21D207296/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN8742L**

Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 2NR5379521

Reg. Date: 30/08/2019 (Man. Year: 2019) Chassis No: MR2B23F3101183644

Colour: White Odometer: 22538 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,837.53	7,597.04	4,240.49	35.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	2,850.00	1,010.00	26.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,697.53	10,447.04	5,250.49	33.45
+ GST 7.00/7.00% (\$\$)	1,098.83	731.29	367.54	33.45
Nett Amount (\$\$)	16,796.36	11,178.33	5,618.03	33.45

INSPECTION

Date of Assignment: 15/12/2021

Date Inspected: 15/12/2021 Inspected At: Vin's Automotive Group (HQ)
160 Sin Ming Drive, #03-03 Sin Ming Autocity
Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount:\$10,447.05

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2022)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN8742L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	751.79 FL	*- FL
2	1		*FRONT BONNET RH HINGE	Not Necessary	53.10 FL	*- FL
3	1		*FRONT BONNET LH HINGE	Not Necessary	53.10 FL	*- FL
4	1		*FRONT RH HEADLAMP	Broken	737.00 FL	*737.00 FL
5	1		*FRONT LH HEADLAMP	Broken	737.00 FL	*737.00 FL
6	1		*FRONT GRILLE BASE	Broken	242.40 FL	*242.40 FL
7	1		*FRONT GRILLE RH OUTER CHROME	Necessary	77.80 FL	*77.80 FL
8	1		*FRONT GRILLE LH OUTER CHROME	Necessary	75.20 FL	*75.20 FL
9	1		*FRONT GRILLE EMBLEM	Necessary	66.20 FL	*66.20 FL
10	1		*FRONT BUMPER	Broken	795.70 FL	*486.00 FL
11	1		*FRONT BUMPER CENTRE GRILLE	Broken	93.30 FL	*93.30 FL
12	1		*FRONT BUMPER LOWER GRILLE	Cut	229.70 FL	*229.70 FL
13	1		*FRONT BUMPER RH DAY LIGHT	Broken	653.60 FL	*350.50 FL
14	1		*FRONT BUMPER LH DAY LIGHT	Broken	653.60 FL	*350.50 FL
15	1		*FRONT BUMPER RH FOG LAMP	Not Necessary	214.20 FL	*- FL
16	1		*FRONT BUMPER LH FOG LAMP	Not Necessary	214.20 FL	*- FL
17	1		*FRONT BUMPER RH FOG LAMP COVER	Not Necessary	84.70 FL	*- FL
18	1		*FRONT BUMPER LH FOG LAMP COVER	Not Necessary	84.70 FL	*- FL
19	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	94.70 FL	*- FL
20	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	94.70 FL	*- FL
21	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	339.30 FL	*- FL
22	10		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
23	1		*REAR BOOTLID	Buckled	685.20 FL	*685.20 FL
24	1		*REAR BOOTLID EMBLEM	Necessary	52.15 FL	*52.15 FL
25	1		*REAR BOOTLID VIOS EMBLEM	Necessary	48.25 FL	*48.25 FL
26	1		*REAR BOOTLID G EMBLEM	Necessary	34.00 FL	*34.00 FL
27	1		*REAR BOOTLID RH REFLECTOR	Cracked	386.53 FL	*386.53 FL
28	1		*REAR BOOTLID LH REFLECTOR	Cracked	386.53 FL	*386.53 FL
29	1		*REAR BOOTLID INNER LOCK	Cut	360.42 FL	*248.30 FL
30	1		*REAR BOOTLID INNER TRIMBOARD	Deformed	349.50 FL	*221.40 FL
31	1		*REAR BOOTLID RUBBER	Twisted	160.40 FL	*160.40 FL
32	1		*REAR BOOTLID RH NO PLATE LIGHT	Cracked	62.20 FL	*62.20 FL
33	1		*REAR BOOTLID LH NO PLATE LIGHT	Not Necessary	62.20 FL	*- FL
34	1		*REAR RH TAILLAMP	Cracked	355.20 FL	*355.20 FL
35	1		*REAR LH TAILLAMP	Cracked	355.20 FL	*355.20 FL
36	1		*REAR BUMPER	Deformed	452.30 FL	*452.30 FL
37	1		*REAR BUMPER RH SIDE RETAINER	Deformed	135.90 FL	*72.70 FL
38	1		*REAR BUMPER LH SIDE RETAINER	Deformed	135.90 FL	*72.70 FL
39	1		*REAR BUMPER REINFORCEMENT	Bent	316.00 FL	*316.00 FL
40	10		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
41	1		*REAR END PANEL	Buckled	620.00 FL	*620.00 FL
42	1		*REAR END PANEL TOP TRIM	Deformed	232.00 FL	*232.00 FL
43	1		*REAR BUMPER ANTENNA SENSOR	Broken	117.10 FL	*117.10 FL
44	1		*REAR BUMPER BUZZIE SENSOR	Not Necessary	144.90 FL	*- FL
45	1		*REAR SPARE TYRE PANEL TOP COVER	Cut	390.20 FL	*206.90 FL
46	1		*REAR RH FENDER	Repair	872.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR LH FENDER	Repair	872.10 FL	*- FL
48	1		*REAR RH FENDER INNER TRIMBOARD	Deformed	355.70 FL	*355.70 FL
49	1		*REAR LH FENDER INNER TRIMBOARD	Deformed	355.70 FL	*355.70 FL
50	20		*REAR RH FENDER INNER TRIMBOARD CLIPS	Necessary	60.00 FL	*60.00 FL
51	1		*REAR LH MUDFLAG	Not Necessary	65.70 FL	*- FL
52	1		*REAR BUMPER PARKING SENSOR	Damaged	280.00 FS	*200.00 FS
53	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
54	1		*REAR NO PLATE	Cut	40.00 FS	*40.00 FS
55	1		*REAR WINDSCREEN GUM	Not Necessary	60.00 FS	*- FS
56	1		*FRONT GRILLE	Cut	77.80 FL	*77.80 FL
57	1		*REAR RH TAILLAMP PANEL	Bent	128.20 FL	*128.20 FL
58	1		*REAR LH TAILLAMP PANEL	Bent	128.20 FL	*128.20 FL
59	1		*REAR LH TAILLAMP LOWER BRACKET	Broken	59.80 FL	*59.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,643.37	10,036.06
- List Item Discount on L Items 25.00/25.00% (S\$)	3,805.84	2,439.02
Total Parts (S\$)	11,837.53	7,597.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DIAGNOSE ELECTRICAL COMPONENTS	New	280.00	30.00
2	TO REMOVE AND REFIX ROOF LINING AND SEAT CUSHION	New	280.00	120.00
3	TO REMOVE AND REFIX PETROL TANK	New	120.00	0.00
4	TO REMOVE AND REFIX REAR WINDSCREEN	New	180.00	0.00
5	TO REPAIR DAMAGES	New	1,400.00	1,200.00
6	TO SPRAY PAINTING	New	1,600.00	1,500.00
Gross Labour Cost (\$)			3,860.00	2,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >