

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21012712/Eqy3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 28/12/2021 SINGAPORE 068811 ATTN: TAN JUN HONG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHD 7250H XD 7656G Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03OED Excess (\$) 0.00 TAN JUN HONG **Assign Date** 15/12/2021 Assign From **Vehicle Particulars & Condition** 2. ISUZU CYZ52K c.c Make & Model 15681 HIDDEN 2013 Engine No. Year of Reg. JALCYZ52KD7000043 WHITE Chassis No. Colour Odometer 521169 KM Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 295/80 R22.5 ALLROUND 4 mm 295/80 R22.5 L/H Front Tyre ALLROUND 4 mm 295/80 R22.5 (D/D) ALLROUND 4/4/4/4 mm R/H Rear Tyre 295/80 R22.5 (D/D) ALLROUND 4/4/4/4 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. 5. **General Information** 11/12/2021 16/12/2021 (09:58 AM) **Accident Date** Inspect Date / Time 7 Penjuru Close Survey held at Repairer VFIX AUTO SERVICE PTE LTD 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$14,000-\$15,000

Report Ref No. CS3/ASM21012712/Eqy3e2

**Estimate Days of Repair** 

**Inspected By** 

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

5b.

CHEN TSUE YEE

Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

5 Working Days